

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026



01) Well Sign: Beeman Oil and Gas LLC – Gladys #2 – API #05-067-09363.

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026



02) Well sign next to electrical control box. Unused, detached dehydrator is on ground. White box trailer and drill rig on right.

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026, 1/12/2026.



03) Beeman Gladys #2 well site. There is an unnecessary equipment not required for operations, including (left to right) a flat bed utility trailer, a box utility trailer, a drill rig, and an old open-topped trailer filled with what appears to be a mixture of oily E&P waste and meteoric water. View looking south.

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026, 1/12/2026.



04) Beeman Gladys #2 well site. There is an unnecessary equipment not required for operations, including (left to right) a pipe/equipment trailer, a box utility trailer, and an old open-topped trailer filled with what appears to be a mixture of oily E&P waste and meteoric water. View looking east. The pump jack and gas combuster are also present.

Inspection Photos for Doc #7211000057
Location Name: Beeman Gladys #2
API # 05-067-09363
Inspector Name: James Blair Inspection Date: 01/09/2026



05) Sign on drill rig: “Enduring Oilfield Services, LLC. 720-697-9330 Bloomfield, NM USDOT 3532172.”

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026



06) Box utility trailer and propane tank are not needed for operations and are being stored on site.

Inspection Photos
Location Name: Beeman Gladys #2
API # 05-067-09363
Inspector Name: James Blair Inspection Date: 01/09/2026



07) Combustor for Gladys 2 in front center of photo

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026



08) Oily rags and trash in plastic barrel with no lid. Fire hazard.

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2


API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026



09) Oily E&P waste is being stored on site in open-topped trailer with no secondary containment. This trailer, and all of the waste on it will need to be moved off site. Waste must be disposed of properly.

Inspection Photos for Doc #7211000057
Location Name: Beeman Gladys #2
API # 05-067-09363
Inspector Name: James Blair Inspection Date: 01/09/2026



10) Oily waste and meteoric water inside 5 gallon bucked left on ground outside of any containment, no lid.

Inspection Photos for Doc #7211000057

Location Name: Beeman Gladys #2

API # 05-067-09363

Inspector Name: James Blair Inspection Date: 01/09/2026



11) Flat bed utility trailer.