

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2026

Submitted Date:

01/13/2026

Document Number:

715801835

FIELD INSPECTION FORM

Loc ID 321488 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293983	WELL	SI	08/01/2025	GW	013-06568	HALEY 32-3	SI

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
	Type Access		
	comment: well is in a planted field		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment: adequate		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
	Comment: red ag panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 2		
	Comment: automation, surface combustion device.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
	Comment:		
Corrective Action:			Date:
Type: Bradenhead	# 1		
	Comment:		
Corrective Action:			Date:

Venting:			
	Yes/No NO		
	Comment:		
Corrective Action:			Date:

Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 293983 Type: WELL API Number: 013-06568 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI all valves are closed, since 7-2025.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/11/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 81 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment: plumbed to surface.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Routine Audit/Inspection Any corrective actions from previous Inspections that have not been addressed are still applicable Weather: Mostly cloudy Temperature: 57* Location: Dry.	revasr	01/13/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801836	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7413658