

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/02/2026

Submitted Date:

01/07/2026

Document Number:

721100042

FIELD INSPECTION FORM

Loc ID 454942 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General		CO2Source_Regulatory@kindermorgan.com	
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454941	WELL	PR	09/01/2021	CO2	033-06184	DC 22	PR
477212	WELL	EP	12/28/2025	LO	033-06186	DC 24	ND

General Comment:

On 1/2/2026 at 1300, I, James Blair performed a compliance audit and inspection at Kinder Morgan's DC 22 carbon dioxide well, API 05-033-06184. It was approximately 50°F and partly cloudy. It had rained earlier and the ground was wet and soft. No others were present. No rig anchor markers were observed. This may be because they are not present, but if they are, they should be marked. No other compliance issues were observed. Photos are attached.

Location

Lease Road:

Type			
comment:	Photo 2		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Photo 1.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	970-882-5522		
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:			Date:

Equipment:

					corrective date
Type: Ancillary equipment	# 1				
Comment:	Solar Telemetry				
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:					
Corrective Action:					Date:
Type: Flow Line	# 1				
Comment:					
Corrective Action:					Date:
Type: Other	# 1				
Comment:	Well head assembly. See photos 3 and 4.				
Corrective Action:					Date:

Type: Deadman # & Marked	# 0	
Comment:	No rig anchors/markers observed. If rig anchors are present, they should be marked.	
Corrective Action:	Comply with 1003 or confirm anchors not present.	Date: 01/09/2026

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 454941 Type: WELL API Number: 033-06184 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477212 Type: WELL API Number: 033-06186 Status: EP Insp. Status: ND

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Gravel	Pass					
Compaction	Pass					
Culverts	Pass					
Rip Rap	Pass	Compaction	Pass			

Comment: [See photos 5 and 6 of riprap and culvert near entrance.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
No compliance issues observed, however reclamation appears to have not improved substantially since 2024 Reclamation Inspection, but needs to be checked during growing season. Corrective actions from previous inspections still apply.	blairj1	01/02/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404498331	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7406418
721100054	Inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7406406