

<b>Date of Inspection</b>	12/30/2025
<b>Inspector Name</b>	Tyson Dilka, Stelbar
<b>Location Name</b>	Young 2-35
<b>API</b>	05-121-10079
<b>COGCC Loc ID</b>	317263
<b>County</b>	Washington
<b>Location Directions</b>	CR 19 & RR, E into
<b>Lat/Long</b>	39.839069, -102.951219
<b>TB Inspected</b>	Former wellsite only
<b>Equipment on Site</b>	No
<b>Livestock Grazing</b>	Yes
<b>Fences</b>	No – removed 12/30/2025
<b>Weeds or Debris</b>	No
<b>Visual of Vegetative Cover</b>	Location is visually observed at 80% overall, small percentage of common weed litter; access road has vehicle tracks in established tall grass, but no rutting
<b>Stormwater</b>	No stormwater issues observed, cattle and burrowing animals have created minor disturbance
<b>Recommendations</b>	Final Reclamation Release
<b>Photos</b>	See below 1-5
<b>Response to Inspection</b>	Photo 6 in document 708201890 states the access road was not re-graded with ruts evident. When driven on, tall established perennial vegetation creates a 2-track in the sandy texture soil. The road in fact does not require additional grading and meets Rule 1004 reclamation requirements. Please reference photo 1 below, without vehicle traffic.



**Photo 1.** Photo facing east showing established vegetation on access road and reference areas.



**Photo 2.** Middle of location facing N.



**Photo 3.** Middle of location facing E.



**Photo 4.** Middle of location facing S.



**Photo 5.** Middle of location facing W.