

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2026

Submitted Date:

01/14/2026

Document Number:

719500800

FIELD INSPECTION FORM

Loc ID 335670 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281864	WELL	PR	02/01/2021	GW	045-11551	N.PARACHUTE EF08B N30 595	PR
281866	WELL	PR	11/02/2006	GW	045-11552	N.PARACHUTE EF02B N30 595	PR
281867	WELL	PR	12/07/2005	GW	045-11553	N.PARACHUTE EF06D N30 595	PR
281868	WELL	PR	11/27/2006	GW	045-11554	N. PARACHUTE EF03B N30 595	PR
281870	WELL	PR	09/25/2006	GW	045-11555	N.PARACHUTE EF02D N30 595	PR
281884	WELL	PR	10/27/2006	GW	045-11556	N.PARACHUTE EF07B N30 595	PR
281887	WELL	PR	12/07/2005	GW	045-11557	N.PARACHUTE EF03D N30 595	PR
281888	WELL	PR	09/01/2023	GW	045-11558	N. PARACHUTE EF06B N30 595	PR
294008	WELL	PR	01/20/2009	GW	045-15200	N. PARACHUTE EF06C-31 N30 59	PR
294009	WELL	PR	08/01/2019	GW	045-15201	N. PARACHUTE EF02A-31 N30 59	PR
294010	WELL	PR	07/06/2008	GW	045-15202	N. PARACHUTE EF02C-31 N30 59	PR
294011	WELL	PR	07/24/2009	GW	045-15203	N.PRACHUTE EF07D-31 N30 59	PR
294012	WELL	PR	08/01/2019	GW	045-15204	N. PARACHUTE EF06A-31 N30 59	PR
294013	WELL	PR	01/12/2009	GW	045-15205	N. PARACHUTE EF03D-31 N30	PR

294014	WELL	PR	06/01/2022	GW	045-15206	N. PARACHUTE EF03A-31 N30 59	PR
294016	WELL	PR	01/07/2009	GW	045-15207	N.PARACHUTE EF08D-31 N30 59	PR
294017	WELL	PR	07/06/2008	GW	045-15208	N.PARACHUTE EF08A-31 N30 59	PR
294018	WELL	PR	07/06/2008	GW	045-15209	N.PARACHUTE EF08C-31 N30 59	PR
294019	WELL	PR	01/06/2009	GW	045-15210	N.PARACHUTE EF07A-31 N30 59	PR
294022	WELL	PR	01/06/2009	GW	045-15211	N. PARACHUTE EF07C-31 N30 59	PR
294023	WELL	PR	01/20/2009	GW	045-15212	N.PARACHUTE EF11A-31 N30 59	PR
294024	WELL	PR	06/01/2023	GW	045-15213	N.PARACHUTE EF11B-31 N30 59	PR
294025	WELL	PR	01/06/2009	GW	045-15214	N.PARCHUTE EF10A-31 N30 59	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 1/13/2026 at approximately 14:25, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, N.PARACHUTE-65S95W/30SESW at Location ID #335670 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Tags hung on the wells are missing required information (API number).		
Corrective Action:	Comply with Rule 605.d.	Date:	02/15/2026

Emergency Contact Number:

Comment:	911/(970)285-2615		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Concrete barriers installed for gas meters/lift and ancillary equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Mobile heaters		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Mobile separator		
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	Line heaters		
Corrective Action:			Date:
Type: Bradenhead	# 20		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	281864	Type:	WELL	API Number:	045-11551	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281866	Type:	WELL	API Number:	045-11552	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281867	Type:	WELL	API Number:	045-11553	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281868	Type:	WELL	API Number:	045-11554	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281870	Type:	WELL	API Number:	045-11555	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281884	Type:	WELL	API Number:	045-11556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281887	Type:	WELL	API Number:	045-11557	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281888	Type:	WELL	API Number:	045-11558	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294008 Type: WELL API Number: 045-15200 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294009 Type: WELL API Number: 045-15201 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294010 Type: WELL API Number: 045-15202 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294011 Type: WELL API Number: 045-15203 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294012 Type: WELL API Number: 045-15204 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294013 Type: WELL API Number: 045-15205 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294014 Type: WELL API Number: 045-15206 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294016	Type:	WELL
API Number:	045-15207	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294017	Type:	WELL
API Number:	045-15208	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294018	Type:	WELL
API Number:	045-15209	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294019	Type:	WELL
API Number:	045-15210	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294022	Type:	WELL
API Number:	045-15211	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294023	Type:	WELL
API Number:	045-15212	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294024	Type:	WELL
API Number:	045-15213	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
				Material Handling And Spill Prevention		
		Culverts				
Gravel						
		Ditches				
Berms						
		Compaction				
Compaction						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	285021	1433412	
	285021	1433412	

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Tags/signs on wellheads are missing required information</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	01/14/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500801	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7415518