

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad  
Location # 481743



Photo # 1267 From entrance to location



Photo # 1268 Sign at entrance to location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



Photo # 1269 Location



Photo # 1270 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743




Photo # 1271 Location



Photo # 1272 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743




Photo # 1273 Location



Photo # 1274 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



Photo # 1275 Location



Photo # 1276 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



Photo # 1277 Location



Photo # 1278 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



Photo # 1279 Location



Photo # 1280 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad  
Location # 481743



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



Photo # 1281 Tank battery lacks required signage



Photo # 1282 Tank battery lacks required signage

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



Photo # 1283 Tank battery lacks required signage



Photo # 1284 Open ended load line

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



**Photo # 1285 Burner exhaust stack on heated 400 bbl condensate tank lacks bird protection/wildlife hazard**



**Photo # 1286 Burner exhaust stack on heated 400 bbl condensate tank lacks bird protection/wildlife hazard**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



**Photo # 1287 Burner exhaust stack on heated 400 bbl condensate tank lacks bird protection/wildlife hazard**



**Photo # 1288 Debris**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



**Photo # 1289 PRV vent line does not comply with CECMC pressure safety device rules (fuel gas supply pot on separator unit)**



**Photo # 1290 PRV vent line does not comply with CECMC pressure safety device rules (fuel gas supply pot on separator unit)**

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



**Photo # 1291 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 1292 PRV vent line does not comply with CECMC pressure safety device rules**

# Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek CC 0697-15-08 Pad

Location # 481743



**Photo # 1293 Plastic containment containing unknown fluid lacks wildlife protection/wildlife hazard**

**Photo # 1294 Plastic containment containing unknown fluid lacks wildlife protection/wildlife hazard**