

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2026

Submitted Date:

01/08/2026

Document Number:

701104429

FIELD INSPECTION FORM

Loc ID 413055 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413086	WELL	PR	09/17/2010	GW	045-18713	BAT 22D-17-07-95	EG
413087	WELL	PR	10/18/2009	GW	045-18714	BAT 23D17-07-95	EG
413088	WELL	PR	08/01/2022	GW	045-18715	BAT 24B-17-07-95	EG
415492	WELL	PR	01/01/2024	GW	045-19066	BAT 34D-17-07-95	EG
415494	WELL	PR	07/19/2010	GW	045-19067	BAT 14D-17-07-95	EG
415528	WELL	PR	07/18/2010	GW	045-19082	BAT 24D-17-07-95	EG
415545	WELL	PR	01/01/2019	GW	045-19089	BAT 44A-18-07-95	EG
415550	WELL	PR	07/24/2015	GW	045-19092	WATSON RANCH B 23A-17-07-95	EG
415560	WELL	PR	07/26/2010	GW	045-19095	BAT 23B-17-07-95	EG
415570	WELL	PR	05/21/2011	GW	045-19098	BAT 13D-17-07-95	EG
415572	WELL	PR	09/15/2015	GW	045-19100	WATSON RANCH B 23C-17-07-95	EG
415573	WELL	PR	09/17/2010	GW	045-19101	BAT 34B-17-07-95	EG
415587	WELL	PR	07/23/2010	GW	045-19108	BAT 13B-17-07-95	EG
415590	WELL	PR	07/18/2010	GW	045-19109	BAT 14B-17-07-95	EG
418498	WELL	PR	12/01/2022	GW	045-19719	WATSON RANCH B 24C-17-07-95	EG
418500	WELL	PR	09/09/2015	GW	045-19721	WATSON RANCH B 24A-17-07-95	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Labels are weathered and peeling.
Install sign to comply with Rule 605.h.
CA Date 2/10/2026

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Labels are weathered and peeling.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 02/10/2026

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No					
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	413086	Type:	WELL	API Number:	045-18713	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	413087	Type:	WELL	API Number:	045-18714	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	413088	Type:	WELL	API Number:	045-18715	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415492	Type:	WELL	API Number:	045-19066	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415494	Type:	WELL	API Number:	045-19067	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415528	Type:	WELL	API Number:	045-19082	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415545	Type:	WELL	API Number:	045-19089	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415550	Type:	WELL	API Number:	045-19092	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415560	Type:	WELL	API Number:	045-19095	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415570	Type:	WELL	API Number:	045-19098	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415572	Type:	WELL	API Number:	045-19100	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415573	Type:	WELL	API Number:	045-19101	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415587	Type:	WELL	API Number:	045-19108	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	415590	Type:	WELL	API Number:	045-19109	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	418498	Type:	WELL	API Number:	045-19719	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	418500	Type:	WELL	API Number:	045-19721	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404499345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7407933
701104430	Flowline integrity inspection 701104429 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7407932