

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date: 10/03/2024

Document Number: 403901235

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 336177 Location Type: Production Facilities
Name: KIYOTA-63N67W Number: 35NWSE
County: WELD
Qtr Qtr: NESE Section: 35 Township: 3N Range: 67W Meridian: 6
Latitude: 40.180460 Longitude: -104.854940

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

When construction of a pipeline occurs near public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and watercourses, flowlines are bored and cased. Applicable permits are acquired prior to construction across county road crossings.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478464 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 331262 Location Type: Well Site
Name: KIYOTA-63N67W Number: 35SESE
County: WELD No Location ID
Qtr Qtr: SESE Section: 35 Township: 3N Range: 67W Meridian: 6
Latitude: 40.176637 Longitude: -104.850712

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 07/26/2001
Maximum Anticipated Operating Pressure (PSI): 450 Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Abandonment Verification

Date: 08/22/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the Kiyota 44-35 (05-123-20398) was removed in its entirety. Bellholes were dug on average every 80 feet and the line pulled. Once the flowline was removed, all areas that needed it were backfilled and the land surface was graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478462 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336272 Location Type: Well Site
Name: KIYOTA-63N67W Number: 35SWSE
County: WELD No Location ID
Qtr Qtr: SWSE Section: 35 Township: 3N Range: 67W Meridian: 6
Latitude: 40.176083 Longitude: -104.855496

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Date Construction Completed: 02/15/2007
Maximum Anticipated Operating Pressure (PSI): Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478461 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 327993 Location Type: Well Site
Name: KIYOTA-63N67W Number: 35NWSE
County: WELD No Location ID
Qtr Qtr: NWSE Section: 35 Township: 3N Range: 67W Meridian: 6
Latitude: 40.178897 Longitude: -104.854412

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 12/07/1991
Maximum Anticipated Operating Pressure (PSI): 460 Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Abandonment Verification

Date: 08/22/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the Kiyota 3-35 (05-123-15404) was removed in its entirety. Bellholes were dug on average every 80 feet and the line pulled. Once the flowline was removed, all areas that needed it were backfilled and the land surface was graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478465 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336177 Location Type: Well Site
Name: KIYOTA-63N67W Number: 35NWSE
County: WELD No Location ID

Qtr Qtr: NESE Section: 35 Township: 3N Range: 67W Meridian: 6

Latitude: 40.180460 Longitude: -104.854940

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: _____ Date Construction Completed: 03/22/2009

Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____

Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478463 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: _____ Location Type: _____ Well Site

Name: KIYOTA-63N67W Number: 35NWSE

County: WELD No Location ID

Qtr Qtr: NWSE Section: 35 Township: 3N Range: 67W Meridian: 6

Latitude: 40.180287 Longitude: -104.856252

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: _____ Date Construction Completed: 02/10/2001

Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____

Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/20/2021

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline serving the Kiyota 33-35 was removed in its entirety

OPERATOR COMMENTS AND SUBMITTAL

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were removed:
12315404_FL: services the Kiyota 3-35 (05-123-15404)
12320398_FL: services the Kiyota 44-35 (05-123-20398)

Updated GIS data attached.
All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 10/03/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ Director of ECMC Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

403901235	Form44 Submitted
403938337	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

Engineer	Update GIS Status from "Abandoned" to "Removed" for all the sections that were removed. Please resubmit by 1/20/2026	01/14/2026
----------	--	------------

Total: 1 comment(s)