

ECMC Inspection Photos - KP Kauffman
Location: Facility #2 Consolidation (1/4/26) Spill ID #492701
Inspection date 01/6/2026 & 1/9/2026



Facility #2 Consolidation 1/4/26 release point; surface expression @ 40.094593, -104.779910 (view looking west)
Inspection date 1/6/26



Facility #2 Consolidation 1/4/26 release point; surface expression @ 40.094593, -104.779910 (view looking east)
Inspection date 1/6/26

ECMC Inspection Photos - KP Kauffman
Location: Facility #2 Consolidation (1/4/26) Spill ID #492701
Inspection date 01/6/2026 & 1/9/2026



Fenced excavation exposing facility #2 consolidation line at area of failure. Inspection date 1/9/26 (view looking west)



KPK Facility #2 consolidation off location flowline exposed in excavation. (1) 8 " CS and (1) 4" HDPE pipe/ material were observed in the excavation. The flowline transitions from 8" CS (to west) to 4" HDPE (to east) in the excavation.

ECMC Inspection Photos - KP Kauffman
Location: Facility #2 Consolidation (1/4/26) Spill ID #492701
Inspection date 01/6/2026 & 1/9/2026



KPK Facility #2 consolidation off location flowline exposed in excavation. (1) 8 " CS and (1) 4" HDPE pipe/ material were observed in the excavation. The flowline transition area has been cut out in preparation for repair (view looking east)



KPK Facility #2 consolidation off location flowline exposed in excavation. (1) 8 " CS and (1) 4" HDPE pipe/ material were observed in the excavation. The flowline transition area has been cut out in preparation for repair (view looking west)