

Final Reclamation Inspection

September 10th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 318186

Inspection Document #: 714003178

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle) and associated tank battery location (blue polygon). Note: no obvious existing road in historic imagery.



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 2. NAIP imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well, presumed flowline, and TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 7. Drone aerial imagery looking downward at the well (displaying the well).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 8. Drone aerial imagery taken south of the tank battery location, facing north (displaying the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 9. Drone aerial imagery taken west of the tank battery location, facing east (displaying the TB, presumed flowline, and well).





Photo 10. Drone aerial imagery taken north of the tank battery location, facing south (displaying the TB).

Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 11. Drone aerial imagery taken east of the tank battery location, facing west (displaying the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 12. Drone aerial imagery looking downward at the TB (displaying part of the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 13. Ground imagery taken from the center of the tank battery location, facing north (displaying the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 14. Ground imagery taken from the center of the tank battery location, facing east (displaying the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 15. Ground imagery taken from the center of the tank battery location, facing south (displaying the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 16. Ground imagery taken from the center of the tank battery location, facing west (displaying the TB).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 17. Ground imagery taken from the tank battery location (displaying the gravel pile).



Inspection Photos

Location Name: UPRR 42 Pan Am AD 1

Location ID: 318186



Photo 18. Ground imagery taken west of the tank battery location (displaying the farm equipment).

