

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



Photo # 87 From entrance to location




Photo # 88 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



Photo # 89 Location



Photo # 90 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



Photo # 91 Location




Photo # 92 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



Photo # 93 Location



Photo # 94 Open ended load line

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



**Photo # 95 Partially buried condensate tank not properly sealed & open to atmosphere (Additionally the open ended piping is also a wildlife hazard)**

**Photo # 96 Partially buried condensate tank not properly sealed & open to atmosphere (Additionally the open ended piping is also a wildlife hazard)**

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



Photo # 97 Labeling on partially buried tank



Photo # 98 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



**Photo # 99 Unused flowline lacks lockout tagout (OOSLAT)  
Line is located in secondary containment near tank heater**

**Photo # 100 Unused flowline lacks lockout tagout (OOSLAT)  
Line is located in secondary containment near tank heater**

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Chevron F06 696 Pad

Location #: 335887



Photo # 101 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 102 Unused flowline lacks lockout tagout (OOSLAT)  
Line is located near pig station