

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2026

Submitted Date:

01/09/2026

Document Number:

708908233

**FIELD INSPECTION FORM**

Loc ID 334980 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 21 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
QB ENERGY		ecmc.inspections@qb-energy.com	
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276862	WELL	PR	06/01/2024	GW	045-10539	PUCKETT 11C-7	PR
290717	WELL	PR	06/01/2024	GW	045-14183	PUCKETT 11D-7D	PR
290718	WELL	PR	06/01/2024	GW	045-14182	PUCKETT 11A-7D	PR
290719	WELL	PR	06/01/2024	GW	045-14181	PUCKETT 11B-7D	SI

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
	Type OTHER		
Comment:	Sign at start of spur road to location		
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
	Type WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:

Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire fence Barbed wire fence needs maintenance/wildlife hazard		
Corrective Action:	Comply with CECMC Rule 602		Date: 01/16/2026

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 276862 Type: WELL API Number: 045-10539 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift  Well lacks wellbore diagram/not in compliance with CECMC Rule 420  Additionally the PUCKETT 11D-7D, PUCKETT 11A-7D & PUCKETT 11B-7D wells also lack wellbore diagrams/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17	Date: <u>02/08/2026</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290717 Type: WELL API Number: 045-14183 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift  Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290718 Type: WELL API Number: 045-14182 Status: PR Insp. Status: PR

**Producing Well**

Comment:	Producing, well on plunger lift  Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290719 Type: WELL API Number: 045-14181 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In     Temporarily Abandoned    Reminder: \_\_\_\_\_

Comment:	Shut In  Well lacks wellbore diagram/not in compliance with CECMC Rule 420	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
		Culverts				
Berms						
		Retention Ponds				
		Gravel				Sparse to none
		Check Dams				
		Ditches				
		Rip Rap				
		Sediment Traps				
		Compaction				Light compaction in some sections
				Material Handling And Spill Prevention		Chemical tank containment
		Drains				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 01/05/2026 at approximately 12:44 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC PUCKETT 11C-7 (Mesa 9) Pad                      Location # 334980 in Garfield County Colorado.                      Location is within High Priority/Black Bear Habitat areas/Greater Sage Grouse General Habitat Management Area &amp; in close proximity to Density Habitat area.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Fencing - Barbed wire fence needs maintenance/wildlife hazard - Comply with Rule 602 with a CA date of 01/16/2026</p> <p>2. Inspected Facilities - All 4 wells on location lack wellbore diagrams - Comply with Rule 420 with a CA date of 02/08/2026</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	smelserw	01/09/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404501478	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410473</a>
708908234	Inspection/Audit 708908233 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410471">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410471</a>
708908235	Inspection/Audit 708908233 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410472</a>