

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2026

Submitted Date:

01/09/2026

Document Number:

715203693

FIELD INSPECTION FORM

Loc ID 321745 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207896	WELL	PR	07/01/2022	OW	017-06831	FRONTERA UNIT 43-13 17	PR

General Comment:

This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh

Location

Lease Road:

	Type Access		
comment:	Gravel road through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
	Type OTHER		
Comment:	Wire panel around cathodic rectifier		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:	Lufkin 160		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 207896 Type: WELL API Number: 017-06831 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Frontera Unit 13, 14, 15, 16, 17, 18, 19, 20\) 1250' SE @ 38.741730/-102.054260](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203737	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7419327