

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/08/2025

Submitted Date:

01/12/2026

Document Number:

720900496

**FIELD INSPECTION FORM**

Loc ID: 303312    Inspector Name: St John, William (Cal)    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE    State: CO    Zip: 80424

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**General Comment:**

On 12/8/2025 Inspector completed a Field Audit of the Bollong 12-1, API #125-06760. This remote gathering facility is south of the Bollong 12-1 well location just off the access trail. The remote facility was also inspected and found to have no signage or documents to ascertain the well/wells that produced to location. Review of electronic well files for the wells in the surrounding area do not reflect this as a related facility. For audit purposes the remote facility has been assigned to the Bollong 12-1 as it is the closest well in the area. Inspector has included a map in the Attachment section of the FIR.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	No Oil and Gas Location/Facility signage at remote gathering facility.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 02/12/2026
Type	TANK LABELS/PLACARDS		
Comment:	No Content/Quantity/Hazard sign at produced water tank.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 02/12/2026
Emergency Contact Number:			
Comment:	No emergency contact information posted at Oil and Gas location.		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 02/12/2026
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Dried weeds and vegetation covering location at time of inspection.		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Production related debris at location.		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Production related equipment items on location and do not appear to be in use at time of inspection.		
Corrective Action:	Comply with Rule 606.		Date: 02/12/2026
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Location post and livestock panel fencing is down and in disrepair. The downed fencing is covered in vegetation creating a trip hazard and possible livestock/wildlife entanglement hazard. Fencing should be repaired or removed.		
Corrective Action:	Repair and maintain fencing to comply with rule 603.h		Date: 01/28/2026
<b>Equipment:</b>			
Type: Other	# 1		corrective date

Comment:	Steel shed. No gas meter inside shed. Steel flowline passes through shed. Valve on flowline appears to be closed at time of inspection. Shed is leaning and appears to be settling in soil or off cribbing.	Date:	
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline riser at location with valve and plug.	Date:	
Corrective Action:		Date:	
Type: Dehydrator	# 2		
Comment:	Dehydrators (Drip Bottle). Valves appear to be closed. **Open ended line with no plug**.	Date:	
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 603.c.(12).	Date:	01/28/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		40.061310,-102.349473
Comment:	Lat/Long taken at tank. No sign/label at tank. Tank does not appear to be in use at time of inspection. Fluid is visible inside tank through opening at tank canter. Opening not covered.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	None.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Flaring:**

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404502276	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7412037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7412037</a>
720900556	Location on Google Map.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7412034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7412034</a>
720900557	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7412035">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7412035</a>