

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2026

Submitted Date:

01/12/2026

Document Number:

721100057

**FIELD INSPECTION FORM**

Loc ID 306991 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 7125  
Name of Operator: BEEMAN OIL & GAS INC  
Address: 13635 E 104TH AVENUE STE 400  
City: COMMERCE CITY State: CO Zip: 80022

**Findings:**

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Galloway, Kelly		kgallowaywerc@gmail.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Lawton, Lisa		lisa@beemanoil.com	
Blair, Jamie		jamie.blair@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290406	WELL	SI	11/01/2023	OW	067-09363	GLADYS 2	SI

**General Comment:**

On Friday, January 09, 2026 Southwest Compliance Specialist James Blair inspected the Beeman Drilling Gladys #2 well. On Monday January 12, I returned to the site to take additional photos. Well conditions did not change but for weather. Observed Endurance drilling rig layed down and stacked out, along with equipment including a white box utility trailer and a flat bed utility trailer. Observed an open top trailer with oily waste and free fluid. Beeman has been cited for similar non-compliance and improper storage of waste on other locations in the past. See document #685200622. Observed various miscellaneous tools and containers. Observed improperly stored trash and oily rags in open-topped plastic container. This inspection focussed work over rig storage, improper E&P waste storage/management. The remote tank battery associated with the well was not inspected.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Unimproved 2 track across pasture can be very muddy if wet.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	OK. See Photo 1 and 2.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-210-2895, or 911		Date:
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Open topped plastic buckets and barrels containing oily waste and trash left on site not necessary for ongoing operations while well is shut in. Photos 8, 9, 10.		
Corrective Action:	Properly dispose and store materials off site to comply with rule 606 and 1002.		Date: 01/16/2026
Type	OTHER		
Comment:	Improperly stored E&P waste in open-topped trailer with no signage. atmospheric controls or wildlife protections. Operator has been cited for similar non-compliance previously. Oily sheen visible. Photo 9. See document #685200622.		
Corrective Action:	Properly dispose off-site and submit receipts and manifests of place and method of disposal to comply with 905 and 906. Submit proof to southwest EPS Jason Kosola.		Date: 01/13/2026
Type	UNUSED EQUIPMENT		
Comment:	drilling rig and associated trailers and equipment improperly stored on-site without approval. 1) Drill Rig. Photo 3, 4, 5. 2) Utility equipment/pipe trailer. Photo 11. 3) White box trailer licence # 63635 TR H. Exp. Mar 2024. Photo 6. 4) Utility trailer with open top E&P waste container. Photo 9. 5) Miscellaneous buckest, tools, etc. photos 2, 3, 4, 5, 6, 7, 8		
Corrective Action:	Remove all unnecessary equipment to comply wih 606 and 1002.		Date: 01/13/2026
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Hog panel fence around electrical panel. Photo 7.		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Other	# 1	
Comment:	well head assembly. Photo 4.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Electrical Panel. Photos 1 & 2.	
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	Photo 4.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Gas Combustor. Photo 7.	
Corrective Action:		Date:

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 290406 Type: WELL API Number: 067-09363 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Move-in and rig up notices and notice of MIT were submitted in September.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Site and access appears to be developed on native soil in pasture with no erosion BMPs.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404504412	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7413414">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7413414</a>
721100058	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7413412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7413412</a>