

# Final Reclamation and Stormwater Inspection

December 31, 2025

Operator: BLUE CREEK INC - 8835

Location ID: 375263

Well Name: DOUBLE BAR O #1

Inspection Document #: 718601280

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 1.** Looking north down the former access road. Original gate has been removed. Desirable perennial vegetation is present on the access road. List C noxious weed cheatgrass is also present on the access road.



**Photo 2.** Looking northwest across the well turn around area.



Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 3.** Picture taken looking west across the south side of the turnaround road. On the south side of the well turnaround area, two depressions are marked with t-posts



**Photo 4.** Picture taken at the center of the well turnaround area. Bare soil is present throughout the location. Undesirable weeds such as russian thistle and kochia are present on the location along with List C noxious weed cheatgrass. Desirable vegetation such as western wheatgrass, crested wheatgrass and blue gramma is also present in limited amounts on location.

Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 5.** Looking east from the center of the well turnaround area. See photo 4 comments.



**Photo 6.** Looking south from the center of the well turnaround area. See photo 4 comments.

Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 7.** Looking west from the center of the well turnaround area. See photo 4 comments.



**Photo 8.** Looking north across the wellbore area. No equipment is present. Bare earth extends approximately 350 ft to the north of the well area. The former access road runs adjacent to the bare area to the east side of this photo.

Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 9.** Picture taken south of the tank battery area looking north across the tank battery southern access road. Bare soil is present in this area.



**Photo 10.** Looking west across the former tank battery area. The access road is visible due to a higher concentration of undesirable weeds. List C noxious weed cheatgrass is present throughout the tank battery location. There appears to be less desirable vegetation establishment on the tank battery location than the surrounding reference areas.



Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 11.** Looking south across the tank battery location and access road. There appears to be slight depressions/subsidence on the tank battery location.



**Photo 12.** Photo taken on the access road near the entrance looking south. The road is slightly contoured and raised. Gravel remains on the access road. Desirable perennial vegetation is present on the access road. List C noxious weed cheatgrass is also present on the access road. Desirable vegetation coverage varies along the length of the access road.

Inspection Photos  
Location Name: DOUBLE BAR O #1  
Location ID: 375263



**Photo 13.** Reference vegetation to the east of the well location. List C noxious weed cheatgrass is present in the reference area. Desirable vegetation such as western wheatgrass, crested wheatgrass, blue gramma, and big bluestem are present throughout the reference area.

