


Inspection Photos

Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Excavation with inadequate fencing

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Excavation with inadequate fencing

Excavation with inadequate fencing

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Excavation with inadequate fencing

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Stockpile with no BMPS

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Stockpile with no BMPS

Stockpile with no BMPS

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Excavation with inadequate fencing

Stockpile with no BMPS

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Stockpile with no BMPS

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039



Trash

Trash

Inspection Photos
Location Name: Cosslett 1,2 Historical
Spill ID: 491039

