

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2026

Submitted Date:

01/15/2026

Document Number:

719500804

**FIELD INSPECTION FORM**

Loc ID 335807 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280531	WELL	PR	10/08/2006	GW	045-11277	N.PARACHUTE EFO6B I30A 595	PR
280532	WELL	PR	10/06/2006	GW	045-11278	N.PARACHUTE EF06D I30A 595	PR
280533	WELL	PR	02/01/2011	GW	045-11279	N.PARACHUTE EF07B I30A 595	PR
280534	WELL	PR	08/15/2006	GW	045-11280	N.PARACHUTE EF07D I30A 595	PR
280535	WELL	PR	08/11/2006	GW	045-11281	N.PARACHUTE EF01B I30A 595	PR
280536	WELL	PR	08/14/2006	GW	045-11282	N.PARACHUTE EF02B I30A 595	PR
280537	WELL	PR	08/11/2006	GW	045-11283	N.PARACHUTE EF02D I30A 595	PR
280538	WELL	PR	09/27/2006	GW	045-11284	N.PARACHUTE EF03D I30A 595	PR
293553	WELL	PR	08/09/2008	GW	045-15048	N. PARACHUTE EF05A-32 I30A 5	PR
293554	WELL	PR	10/13/2008	GW	045-15049	N. PARACHUTE EF05C-32 I30A 5	PR
293555	WELL	PR	03/27/2008	GW	045-15050	N. PARACHUTE EF04C-32 I30A 5	PR
293556	WELL	PR	09/19/2007	GW	045-15051	N. PARACHUTE EF02C-30 I30A 5	PR
293557	WELL	PR	02/01/2011	GW	045-15047	N. PARACHUTE EF16A-30 I30A 5	PR
293558	WELL	PR	08/09/2008	GW	045-15046	N. PARACHUTE EF02A-30-I30A 5	PR

293559	WELL	PR	11/19/2007	GW	045-15059	N. PARACHUTE EF15D-19 I30A 5	PR
293560	WELL	PR	08/14/2009	GW	045-15060	N. PARACHUTE EF15C-19 I30A 5	PR
293680	WELL	PR	10/13/2008	GW	045-15096	N. PARACHUTE EF03C-30 I30A 5	PR
293681	WELL	PR	10/06/2008	GW	045-15097	N. PARACHUTE EF03A-30 I30A 5	PR
293682	WELL	PR	10/11/2008	GW	045-15098	N. PARACHUTE EF03B-30 I30A 5	PR
293683	WELL	PR	10/14/2008	GW	045-15099	N. PARACHUTE EF06A-30 I30A 5	PR
293684	WELL	PR	10/06/2008	GW	045-15100	N. PARACHUTE EF06C-30 I30A 5	PR
293685	WELL	PR	08/09/2008	GW	045-15101	N. PARACHUTE EF07A-30 I30A 5	PR
293686	WELL	PR	10/12/2008	GW	045-15102	N. PARACHUTE EF07C-30 I30A 5	PR
293687	WELL	PR	10/03/2008	GW	045-15103	N. PARACHUTE EF16C-30 I30A 5	PR
293688	WELL	PR	10/03/2008	GW	045-15104	N. PARACHUTE EF01A-31 I30A 5	PR
293689	WELL	PR	10/13/2008	GW	045-15105	N. PARACHUTE EF01C-31 I30A 5	PR
293690	WELL	PR	09/01/2008	GW	045-15106	N. PARACHUTE EF05D-32 I30A 5	PR
293691	WELL	PR	08/09/2008	GW	045-15107	N. PARACHUTE EF14D-19 I30A 5	PR

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 1/13/2026 at approximately 14:35, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, N.PARACHUTE-65S95W/30NESE at Location ID #335807 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Tags hung on the wells are missing required information (API number).		
Corrective Action:	Comply with Rule 605.d.	Date:	02/16/2026

**Emergency Contact Number:**

Comment:	911/(970)285-2615	Date:	
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Concrete barriers installed at gas meters/lift and ancillary equipment		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Ancillary equipment	# 2		
Comment:	Line heaters		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Gas lit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment: <a href="#">Mobile separators</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 20	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 8	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 20	
Comment: <a href="#">Gas lit</a>		
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment: <a href="#">Chemical tanks</a>		
Corrective Action:		Date:
Type: Gas Meter Run	# 8	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 8	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment: <a href="#">Corrosion present on AST.</a>					
Corrective Action: <a href="#">All in-service Tanks and process vessels will be inspected and maintained pursuant to applicable standards.</a>		Date:	02/16/2026		

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	280531	Type:	WELL	API Number:	045-11277	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280532	Type:	WELL	API Number:	045-11278	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280533	Type:	WELL	API Number:	045-11279	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280534	Type:	WELL	API Number:	045-11280	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280535	Type:	WELL	API Number:	045-11281	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280536	Type:	WELL	API Number:	045-11282	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280537	Type:	WELL	API Number:	045-11283	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280538	Type:	WELL	API Number:	045-11284	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293553 Type: WELL API Number: 045-15048 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293554 Type: WELL API Number: 045-15049 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293555 Type: WELL API Number: 045-15050 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293556 Type: WELL API Number: 045-15051 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293557 Type: WELL API Number: 045-15047 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293558 Type: WELL API Number: 045-15046 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293559 Type: WELL API Number: 045-15059 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293560	Type:	WELL
API Number:	045-15060	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293680	Type:	WELL
API Number:	045-15096	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293681	Type:	WELL
API Number:	045-15097	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293682	Type:	WELL
API Number:	045-15098	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293683	Type:	WELL
API Number:	045-15099	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293684	Type:	WELL
API Number:	045-15100	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293685	Type:	WELL
API Number:	045-15101	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID: 293686 Type: WELL API Number: 045-15102 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293687 Type: WELL API Number: 045-15103 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293688 Type: WELL API Number: 045-15104 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293689 Type: WELL API Number: 045-15105 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293690 Type: WELL API Number: 045-15106 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293691 Type: WELL API Number: 045-15107 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
				Material Handling And Spill Prevention		
		Culverts				
Gravel						
		Gravel				
		Compaction				
Compaction						
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Tags/signs on wellheads are missing required information                      2) Corrosion present on produced water AST</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	01/15/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404508453	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417509</a>
719500805	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417507">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417507</a>