

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2026

Submitted Date:

01/15/2026

Document Number:

719500806

FIELD INSPECTION FORM

Loc ID 335588 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280381	WELL	PR	02/01/2014	GW	045-11246	N.PARACHUTE EF01B 130 595	PR
280387	WELL	PR	04/12/2007	GW	045-11251	N.PARACHUTE EF08B 130 595	PR
280388	WELL	PR	09/17/2008	GW	045-11250	N.PARACHUTE EF 08D 130 595	PR
280389	WELL	PR	07/20/2006	GW	045-11249	N.PARACHUTE EF 16D 130 595	PR
280390	WELL	PR	04/19/2007	GW	045-11248	N.PARACHUTE EF16B I30 595	PR
280391	WELL	PR	06/22/2006	GW	045-11247	N.PARACHUTE EF04B 130 595	PR
280439	WELL	PR	02/01/2014	GW	045-11252	N.PARACHUTE EF01D-31 I30 59	PR
280440	WELL	PR	07/21/2006	GW	045-11253	N. PARACHUTE EF01D I30 595	PR
294239	WELL	PR	01/01/2021	GW	045-15341	N. PARACHUTE EF16C-19 I30 59	PR
294240	WELL	PR	01/01/2021	GW	045-15342	N. PARACHUTE EF03A-29 I30 59	PR
294241	WELL	PR	02/24/2009	GW	045-15343	N. PARACHUTE EF05C-29 I30 59	PR
294242	WELL	PR	02/11/2009	GW	045-15344	N.PARACHUTE EF12D-29 I30 59	PR
294261	WELL	PR	02/20/2009	GW	045-15345	N.PARACHUTE EF13A-29 I30 59	PR
294262	WELL	PR	08/11/2009	GW	045-15346	N. PARACHUTE EFO1B-30 I30 59	PR

294263	WELL	PR	02/20/2009	GW	045-15347	N.PARACHUTE EF13C-29 I30 59	PR
294264	WELL	PR	07/20/2009	GW	045-15348	N. PARACHUTE EF04D-29 I30 59	PR
294265	WELL	PR	07/25/2009	GW	045-15349	N. PARACHUTE EF04C-29 I30 59	PR
294266	WELL	PR	02/11/2009	GW	045-15350	N. PARACHUTE EF05A-29 I30 59	PR
294267	WELL	PR	07/27/2009	GW	045-15351	N.PARACHUTE EF08A-30 I30 59	PR
294268	WELL	PR	08/17/2009	GW	045-15352	N.PARACHUTE EF08C-30 I30 59	PR
294269	WELL	PR	03/22/2009	GW	045-15353	N.PARACHUTE EF04A-32 I30 59	PR
294270	WELL	PR	02/19/2009	GW	045-15354	N.PARACHUTE EF05D-29 I30 59	PR
294271	WELL	PR	09/15/2009	GW	045-15355	N. PARACHUTE EF04A-29 I30 59	PR
294272	WELL	PR	07/28/2009	GW	045-15356	N. PARACHUTE EF16D-19 I30 59	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 1/13/2026 at approximately 14:40, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, EF I30 595 at Location ID #335588 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Tags hung on the wells are missing required information (API number).		
Corrective Action:	Comply with Rule 605.d.	Date:	02/16/2026
Emergency Contact Number:			
Comment:	911/(970)285-2615		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Stored supplies near mobile separators.		
Corrective Action:	Remove stored supplies.	Date:	01/23/2026
Type	WEEDS		
Comment:	Weeds across north end of location.		
Corrective Action:	Remove weeds.	Date:	01/23/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Concrete barriers installed at gas meters/lift and ancillary equipment.		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 20		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 4		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Mobile separators		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Line heater		
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Bradenhead	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	280381	Type:	WELL	API Number:	045-11246	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280387	Type:	WELL	API Number:	045-11251	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280388	Type:	WELL	API Number:	045-11250	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280389	Type:	WELL	API Number:	045-11249	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280390	Type:	WELL	API Number:	045-11248	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280391	Type:	WELL	API Number:	045-11247	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280439	Type:	WELL	API Number:	045-11252	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	280440	Type:	WELL	API Number:	045-11253	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294239 Type: WELL API Number: 045-15341 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294240 Type: WELL API Number: 045-15342 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294241 Type: WELL API Number: 045-15343 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294242 Type: WELL API Number: 045-15344 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294261 Type: WELL API Number: 045-15345 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294262 Type: WELL API Number: 045-15346 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294263 Type: WELL API Number: 045-15347 Status: PR Insp. Status: PR

Producing Well			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294264	Type:	WELL
API Number:	045-15348	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294265	Type:	WELL
API Number:	045-15349	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294266	Type:	WELL
API Number:	045-15350	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294267	Type:	WELL
API Number:	045-15351	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294268	Type:	WELL
API Number:	045-15352	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294269	Type:	WELL
API Number:	045-15353	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294270	Type:	WELL
API Number:	045-15354	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID: 294271 Type: WELL API Number: 045-15355 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294272 Type: WELL API Number: 045-15356 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
		Compaction				
Gravel						
		Culverts				
Compaction						
				Material Handling And Spill Prevention		
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Tags/signs on wellheads are missing required information 2) Weeds on location 3) Stored supplies on location</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	01/15/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404508454	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417510
719500807	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417508