

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

09/09/2024

Document Number:

403841412

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmillier@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 336389 Location Type: Production Facilities
Name: DONIPHAN SHIELDS NENE MULTI-WELL Number: 8-4-11
County: BOULDER
Qtr Qtr: NENE Section: 11 Township: 1N Range: 69W Meridian: 6
Latitude: 40.070350 Longitude: -105.077970

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 479662 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321469 Location Type: Well Site
Name: BAILEY-61N69W Number: 12NWNW
County: BOULDER No Location ID
Qtr Qtr: NWNW Section: 12 Township: 1N Range: 69W Meridian: 6
Latitude: 40.071176 Longitude: -105.072837

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: _____ Date Construction Completed: 03/01/2007
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 479661 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321485 Location Type: Well Site
Name: DONIPHAN SHIELDS-61N69W Number: 11SWNE
County: BOULDER No Location ID
Qtr Qtr: SWNE Section: 11 Township: 1N Range: 69W Meridian: 6
Latitude: 40.067860 Longitude: -105.081106

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 12/06/2008
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Abandonment Verification

Date: 06/12/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
County	BOULDER	N/A

Description of Abandonment Verification:

<p>The flowline serving the DONIPHAN SHIELDS 32-11 (05-013-06557) was partially abandoned in place as per Rule 1105.d and verified by a third party. The flowline segment running under Kenosah Road and ending at the tank battery was abandoned in place, the remainder of the flowline was removed. Where the flowline segment was removed, all bellholes were backfilled and the land surface graded.</p>

OPERATOR COMMENTS AND SUBMITTAL

<p>Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were partially abandoned in place and partially removed: 01306557_FL: serviced Doniphan Shields 32-11 (05-013-06557)</p> <p>Third party verification attached. Updated GIS data attached.</p> <p>The 01306557_FL was abandoned in place and does not have any associated spill/releases reported on a Form 19. All other related flowlines will remain as previously reported.</p>

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 09/09/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ **Director of ECMC** Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

403841412	Form44 Submitted
403841433	THIRD PARTY VERIFICATION
403878421	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

Engineer	Pressure test not submitted. Update GIS Status from "Abandoned" to "Removed" for all the sections that were removed. Please resubmit by 1/20/2026	01/09/2026
----------	--	------------

Total: 1 comment(s)