

Inspection Photos  
Well Name: HUBER-ARADO 1-13  
LOCATION ID:326308



Inspection Photos  
Well Name: HUBER-ARADO 1-13  
LOCATION ID:326308



Inspection Photos  
Well Name: HUBER-ARADO 1-13  
LOCATION ID:326308



Inspection Photos  
Well Name: HUBER-ARADO 1-13  
LOCATION ID:326308



Inspection Photos  
Well Name: HUBER-ARADO 1-13  
LOCATION ID:326308



1 in FLOW LINE

Inspection Photos  
Well Name: HUBER-ARADO 1-13  
LOCATION ID:326308



**NO SPILL PREVENTION**