

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>01/21/2026</u> Submitted Date: <u>01/22/2026</u> Document Number: <u>719001180</u>
FIELD INSPECTION FORM			

Loc ID _____ Inspector Name: GARCIA, CHARLES On-Site Inspection
 326308 _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

3 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216208	WELL	PR	05/01/2018	CBM	067-07814	HUBER-ARADO 1-13	PR

General Comment:

[Inspection Report Summary](#)
 On 1/21/26 | Inspector Charles Garcia conducted an on-site inspection.
 Location: HUBER-ARADO 1-13
 API# 067-07814
 Operator: HILLCORP ENERGY COMPANY
 County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	WOODEN PELLETS ON SOUTH SIDE OF LOCATION see location pictures		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	WOODEN PELLETS ON SOUTH SIDE OF LOCATION "appears 1' flowline on edge of location is not necessary for ongoing oil and gas operations"		
Corrective Action:	Return to service or properly abandon per 1100 series rules or explain why flowline is necessary for ongoing operations via FIRR		Date: 04/22/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	ONE UNMARKED SEE LOCATION PICTURES		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER FOR PRIME MOVER NO SPILL PREVENTION		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	LUBE OIL CONTAINER FOR PRIME MOVER NO SPILL PREVENTION location pictures		
Corrective Action:	Materials Handling and Spill Prevention Procedures and practices per rule 1002.f.(2)B		Date: 01/25/2026
Type: Flow Line	# 1		
Comment:	1", IN FLOW LINE not in use and open ended/no OOSLAT SEE LOCATION PICTURES		
Corrective Action:	OOSLAT pre rule 1101.a (3)		Date: 01/25/2026

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216208 Type: WELL API Number: 067-07814 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001181	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7423587