

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 1 – Location Placard at entrance to location

Photo 2 – Placard at Tank Battery

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 3 – Impacted soils

Photo 4 – Impacted soils under tanks

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 5 – impacted soils

Photo 6 – impacted soils

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 7 – Impacted soils

Photo 8 – Impacted Soils

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 9 – Impacted soils east side of tanks.

Photo 10 – Impacted soils east side of tanks.

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 11 – Impacted soils east side of tanks.

Photo 12 – Impacted soils east side wall of excavation

Inspection Photos
Location: Trade Winds 1-28
Location ID: 413318
API # 05-061-06838



Photo 13 – Spoil Pile

Photo 14 – Spoil pile on liner