

Inspection Photos  
Location Name: Carl Miller Consolidation  
Spill ID: 489817



Excavation fencing has fallen. Weeds growing through it.

Excavation fencing has fallen. Weeds growing through it.

**Inspection Photos**  
**Location Name: Carl Miller Consolidation**  
**Spill ID: 489817**



**Excavation fencing has fallen. Weeds growing through it.**

**Stockpile no liner of BMPs**


**Inspection Photos**  
**Location Name: Carl Miller Consolidation**  
**Spill ID: 489817**



**Stockpile no liner of BMPs**

**Stockpile with liner torn**



**Inspection Photos**  
**Location Name: Carl Miller Consolidation**  
**Spill ID: 489817**



**Stockpile with liner torn**

**Stockpile with liner torn**

**Inspection Photos**  
**Location Name: Carl Miller Consolidation**  
**Spill ID: 489817**



**Stockpile with liner torn**

**Stockpile with liner torn**

