

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/22/2026

Document Number:

717300704

FIELD INSPECTION FORM

Loc ID 417609 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417604	WELL	PA		OW	123-31701	KERN L 04-20D	PA
417609	LOCATION	AC			-	KERN L 04-20D, 04-32D	EG
490235	SPILL OR RELEASE	CL	05/22/2025		-	Kern L04-20D, 32D Facility	CL

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 417604 Type: WELL API Number: 123-31701 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 417609 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 490235 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Wells (2) are plugged and abandoned (2025); The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #404137920 received on 03/24/2025. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is nearing completion.	maclarej	01/22/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300710	Facility/ battery; decommissioned	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424211
717300711	PA well location; view SW to facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424212