

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

10/18/2024

Document Number:

403898734

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 473525 Location Type: Production Facilities
Name: EDITH ANN-62N68W Number: 21NESE
County: WELD
Qtr Qtr: NESE Section: 21 Township: 2N Range: 68W Meridian: 6
Latitude: 40.123111 Longitude: -105.001647

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473542 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 336416 Location Type: Well Site
Name: JILLSON 'A'-62N68W Number: 21NWSE
County: WELD No Location ID
Qtr Qtr: NWSE Section: 21 Township: 2N Range: 68W Meridian: 6
Latitude: 40.122330 Longitude: -105.005940

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 04/25/2002
Maximum Anticipated Operating Pressure (PSI): 175 Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Abandonment Verification

Date: 08/09/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
County	WELD	N/A

Description of Abandonment Verification:

The flowline serving the EDITH ANN 33-21(05-123-20624) was partially abandoned in place as per Rule 1105.d and verified by a third party. See attached exhibit. The flowline segment from the wellhead to pipeline crossings was removed, the remainder was abandoned in place. Where the flowline segment was removed, all bellholes were backfilled and the land surface graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473541 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 323300 Location Type: Well Site
Name: EDITH ANN-62N68W Number: 21NESE
County: WELD No Location ID
Qtr Qtr: NESE Section: 21 Township: 2N Range: 68W Meridian: 6
Latitude: 40.121457 Longitude: -105.002196

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 05/04/1996
Maximum Anticipated Operating Pressure (PSI): 185 Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/13/2022

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline servicing the Edith Ann 1-2 (05-123-12833) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 4/12/2018.

OPERATOR COMMENTS AND SUBMITTAL

Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowline was partially abandoned in place and partially removed:
12320624_FL: services the EDITH ANN 33-21(05-123-20624)

Third party verification attached.
Updated GIS data attached.
All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 10/18/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ **Director of ECMC** Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

403898734	Form44 Submitted
403935922	THIRD PARTY VERIFICATION
403936012	OFF-LOCATION FLOWLINE GIS SHP
403947808	PROPOSED ABANDONMENT LAYOUT DRAWING

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

Engineer	Submit pressure test for abandonment in place. Update GIS Status from "Abandoned" to "Removed" for all the sections that were removed. Please resubmit by 1/23/2026	01/16/2026
----------	--	------------

Total: 1 comment(s)