

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/22/2026

Document Number:

715203817

FIELD INSPECTION FORM

Loc ID 303630 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253400	WELL	PR	01/03/1991	GW	125-07277	CRANMER 4-27	PR

General Comment:

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

Location				
Lease Road:				
	Type	Access		
	comment:	No trail to wellhead. Access wellhead through pasture		
	Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	Lease sign by wellhead		
	Corrective Action:		Date:	
Emergency Contact Number:				
	Comment:	<input style="width: 100%;" type="text"/>		
	Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	WELLHEAD		
	Comment:	Pipe fence around wellhead		
	Corrective Action:		Date:	
Venting:				
	Yes/No			
	Comment:			
	Corrective Action:		Date:	
Flaring:				
	Type			
	Comment:			
	Corrective Action:		Date:	

Inspected Facilities

Facility ID: 253400 Type: WELL API Number: 125-07277 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Cranmer 1-27, 4-27, 31-27, 33-27, Heath 42-27, 43-27, Renzelman 41-27\) 1600' NNE @ Cranmer 1-27](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: [Location is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203833	wellhead photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424609