

Inspection Photos

Location Name: TEP Rocky Mountain LLC MAHAFFEY PA 24-32 Pad

Location # 323949



Photo # 4381 From entrance to location

Photo # 4382 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MAHAFFEY PA 24-32 Pad

Location # 323949



Photo # 4383 Location



Photo # 4384 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MAHAFFEY PA 24-32 Pad

Location # 323949




Photo # 4385 Location



Photo # 4386 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC MAHAFFEY PA 24-32 Pad

Location # 323949



Photo # 4387 Location




Photo # 4388 Observed valve on BH line going to ECD closed & tagged out

Inspection Photos

Location Name: TEP Rocky Mountain LLC MAHAFFEY PA 24-32 Pad

Location # 323949



Photo # 4389 Observed valve on BH line going to ECD closed & tagged out

Photo # 4390 Unused flowline lacks lockout tagout (OOSLAT)

Inspection Photos

Location Name: TEP Rocky Mountain LLC MAHAFFEY PA 24-32 Pad

Location # 323949



Photo # 4391 Unused flowline lacks lockout tagout (OOSLAT)