

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/23/2026

Document Number:

701104465

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312605 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 10433 _____
Name of Operator: LARAMIE ENERGY LLC _____
Address: 1700 LINCOLN ST STE 3950 _____
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80203 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 _____ Number of Comments
- 1 _____ Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222004	WELL	PR	03/01/2021	GW	077-08606	WAGON TRAIL 44-11	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Inspect and verify integrity of separator.
Comply with Rule 608.e
CA Date 2/7/2026

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Separator has large area of rust on one side.		
Corrective Action:	Inspect and verify integrity of separator. Comply with Rule 608.e	Date:	02/07/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:	Paint is gone around bottom of tank.				
Corrective Action:				Date:	

Paint

Condition: Inadequate

Other (Content): _____

Other (Capacity): _____

Other (Type): _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 222004 Type: WELL API Number: 077-08606 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104466	Flowline integrity inspection 701104465 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425751