

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2026

Submitted Date:

01/23/2026

Document Number:

708908332

FIELD INSPECTION FORM

Loc ID 323949 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211336	WELL	PR	03/12/2005	GW	045-07096	MAHAFFEY PA 24-32	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Solar powered air compressor - hog panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	SENSORFIELD monitoring device & Taylor plug located on bradenhead, bradenhead valve is accessible BH line tied into ECD - Observed valve on BH line going to ECD closed & tagged out - please refer to photo log		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Solar powered air compressor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Unused flowline lacks lockout tagout (OOSLAT)		
Corrective Action:	Comply with CECMC Rule 1101	Date:	01/30/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)	80 bbl		
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 211336 Type: WELL API Number: 045-07096 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/02/2025 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 105 Fluid Type: WATER AND GAS

End Surf Csg Pressure: 0

Comment: BH line tied into ECD

FORM 4 SUNDRY document #'s 404030162, 404328484 & 404390163

FORM 42 document # 404360883

Observed valve on BH line going to ECD closed & tagged out - please refer to photo log

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
		Gravel				Sparse to none in most sections
		Compaction				Small amount of light compaction
Rip Rap						
Berms						
		Culverts				
Gravel						Sparse to none in most areas
Sediment Traps						
		Tracking Pad				FODS trackout mats & gravel at start of lease road

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 01/22/2026 at approximately 15:04 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC MAHAFFEY PA24-32 Pad. Location # 323949 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost sites & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water External Buffer & in close proximity to Rule 411b Generalized External Buffer. Location is approximately 50 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - Unused flowline lacks lockout tagout (OOSLAT) - Comply with Rule 1101 with a CA date of 01/30/2026</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	01/23/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908333	Inspection/Audit 708908332 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425767

708908334	Inspection/Audit 708908332 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425768
-----------	---	---