

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/23/2026

Document Number:

708908338

FIELD INSPECTION FORM

Loc ID 335420 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
21 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277326	WELL	PR	08/29/2005	GW	045-10669	CHEVRON GM 523-20	PR
277327	WELL	PR	09/07/2005	OW	045-10670	CHEVRON GM 423-20	PR
277328	WELL	PR	08/29/2005	OW	045-10671	CHEVRON GM 323-20	PR
277329	WELL	PR	08/26/2005	GW	045-10672	CHEVRON GM 23-20	PR

General Comment:
[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:	CHEVRON GM 423-20 well has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible CHEVRON GM 523-20, CHEVRON GM 323-20 & CHEVRON GM 23-20 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	Comply with CECMC Rule 603	Date:	01/30/2026
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:	Paint peeling & tank starting to rust in multiple areas - please refer to photo log Tank equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277326	Type:	WELL	API Number:	045-10669	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	277327	Type:	WELL	API Number:	045-10670	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	277328	Type:	WELL	API Number:	045-10671	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	277329	Type:	WELL	API Number:	045-10672	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap				
		Sediment Traps				
		Check Dams				
		Compaction				Light compaction in some sections
		Gravel				Sparse to none in most sections
		Ditches				
Gravel						Sparse to none in most areas
		Culverts				
Compaction						Small amount of light compaction

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 01/21/2026 at approximately 13:34 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at TEP ROCKY MOUNTAIN LLC CHEVRON GM 23 -20 Pad Location # 335420 in Garfield County Colorado. Please refer to inspection/audit 708303076 conducted on 11/14/2024, previous corrective action has been completed. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - Open ended load line - Comply with Rule 603 with a CA date of 01/30/2026</p> <p>Comments -</p> <p>Tanks & Berms - Paint peeling & production tank starting to rust in multiple areas</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	01/23/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908339	Inspection/Audit 708908338 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425912

708908340	Inspection/Audit 708908338 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425913
-----------	---	---