

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2026

Submitted Date:

01/24/2026

Document Number:

708908344

**FIELD INSPECTION FORM**

Loc ID 324126 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258167	WELL	PR	10/03/2000	GW	045-07622	CHEVRON GM 33-20	PR

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
	Type TANK LABELS/PLACARDS		
Comment:	Capacity on tank label faded & becoming illegible - Please refer to photo log CA will be issued in next inspection if issue remains unaddressed		
Corrective Action:		Date:	
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
	Type BATTERY		
Comment:			
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
	Comment: 911/970-285-9377		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No  
 Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
	Type OTHER		
Comment:	Air compressor - hog panels		
Corrective Action:		Date:	
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Catle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Air compressor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Burner exhaust open ended/wildlife hazard/available for entry by wildlife Flanged piping on separator unit open ended/wildlife hazard/available for entry by wildlife Hole in separator roof/wildlife hazard/available for entry by wildlife		
Corrective Action:	Comply with CECMC Rules 602 & 608	Date:	01/31/2026

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:				Date:	

<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)	210 bbl				

Other (Type) _____	
--------------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 258167 Type: WELL API Number: 045-07622 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in most areas
		Culverts				
Compaction						Light compaction in some areas
		Sediment Traps				
		Ditches				
		Rip Rap				
		Check Dams				
		Compaction				Light compaction in some sections
		Gravel				Sparse to none in most sections

Comment:

Corrective Action:

Date:

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 01/22/2026 at approximately 13:42 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at TEP ROCKY MOUNTAIN LLC CHEVRON GM 33 -20 Pad                      Location # 324126 in Garfield County Colorado.                      Please refer to inspection/audit 708303072 conducted on 11/12/2024, previous corrective actions have been completed.                      Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.                      Location is approximately 6 yards from Jangle Ditch.                      Location is approximately 194 yards from Parachute Creek.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - Burner exhaust open ended/wildlife hazard, Flanged piping on separator unit open ended/wildlife hazard &amp; Hole in separator roof/wildlife hazard - Comply with Rules 602 &amp; 608 with a CA date of 01/31/2026</p> <p>Comments -</p> <p>Signs/Marker - Capacity on tank label faded &amp; becoming illegible</p> <p>Split pad/Remote location - Shared facilities with the CHEVRON GM 34-20 location # 335313</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	smelserw	01/24/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908345	Inspection/Audit 708908344 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425969">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425969</a>