

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

11/07/2024

Document Number:

403934231

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 333126 Location Type: Production Facilities
Name: MEREDITH-62N68W Number: 26NESE
County: WELD
Qtr Qtr: NESE Section: 26 Township: 2N Range: 68W Meridian: 6
Latitude: 40.107721 Longitude: -104.963267

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473778 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 333126 Location Type: Well Site
Name: MEREDITH-62N68W Number: 26NESE
County: WELD No Location ID
Qtr Qtr: NESE Section: 26 Township: 2N Range: 68W Meridian: 6
Latitude: 40.107721 Longitude: -104.963267

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 10/25/2008
Maximum Anticipated Operating Pressure (PSI): 285 Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Abandonment Verification

Date: 09/20/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the SULLIVAN 8-6-26 (05-123-26475) was removed in its entirety. Bellholes were dug on average every 80 feet and the line pulled. Once the flowline was removed, all areas that needed it were backfilled and the land surface was graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 479342 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 333126 Location Type: Well Site
Name: MEREDITH-62N68W Number: 26NESE
County: WELD No Location ID
Qtr Qtr: NESE Section: 26 Township: 2N Range: 68W Meridian: 6
Latitude: 40.107721 Longitude: -104.963267

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 3.000
Bedding Material: Native Materials Date Construction Completed: 03/10/1976
Maximum Anticipated Operating Pressure (PSI): 27 Testing PSI: 32
Test Date: 07/22/2015

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 479341 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 333163 Location Type: Well Site

Name: Sullivan Number: 26H-P268

County: WELD No Location ID

Qtr Qtr: SESE Section: 26 Township: 2N Range: 68W Meridian: 6

Latitude: 40.104095 Longitude: -104.962853

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Fiberglass Max Outer Diameter:(Inches) 3.000

Bedding Material: Native Materials Date Construction Completed: 04/09/1978

Maximum Anticipated Operating Pressure (PSI): 21 Testing PSI: 25

Test Date: 05/31/2017

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473779 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 332899 Location Type: Well Site

Name: JOHNSON-62N68W Number: 26NWSE

County: WELD No Location ID

Qtr Qtr: NWSE Section: 26 Township: 2N Range: 68W Meridian: 6

Latitude: 40.107419 Longitude: -104.968530

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: _____ Date Construction Completed: 07/19/2007

Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____

Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 09/08/2022

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline 12321936_FL serving the Sullivan 33-26 (05-123-21936) was removed in its entirety via the open trench method. The trench was backfilled and the land surface was graded.

OPERATOR COMMENTS AND SUBMITTAL

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline was removed:
12326475_FL: services the SULLIVAN 8-6-26 (05-123-26475)

Updated GIS data attached.
All other related flowlines will remain as previously reported.

The Meredith 1 and Meredith 2 flowlines are registered under the same end location (333126) but are not owned by Crestone. Therefore, these lines are not included in the attached GIS data.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 11/07/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ **Director of ECMC** Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

403934231	Form44 Submitted
403985789	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

Engineer	Update GIS Status from "Abandoned" to "Removed". Please resubmit by 1/28/2026	01/19/2026
----------	---	------------

Total: 1 comment(s)