

Final Reclamation Inspection

January 2, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 329406

Inspection Document #: 718801255

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BECKER #5-11
Location ID: 329406



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #5-11
Location ID: 329406



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #5-11
Location ID: 329406



Photo 5. Photo taken of ground cover at the location. Photo illustrates perennial grass, bare ground, and drill rows from seeding.



Photo 6. Photo taken of the access road to the location, facing west. Photo illustrates that this portion of the access road to the location remains unreclaimed. Stormwater erosion was observed along the road (circled in red).

Inspection Photos
Location Name: BECKER #5-11
Location ID: 329406



Photo 7. Photo taken of the access road to the location, from the location, facing northwest. Photo illustrates that this portion of the access road has been reclaimed, with evidence of drill row seeding. However, vegetation establishment does not meet Rule 1004 standards.



Photo 8. Photo taken of the reference area to the location, southwest of the location, facing southwest. Photo illustrates perennial grass and weedy annual vegetation.