

# Final Reclamation and Stormwater Inspection

January 20, 2026

Operator: WESTERN INTERIOR ENERGY INC - 95750

Location ID: 319953

Well Name: HILTON #1

Inspection Document #: 718601305

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 1.** Picture taken on wolf creek rd looking south. Three oilfield pipes are present near the entrances to the tank battery (red circles).



**Photo 2.** An underground gas line ground test station is present on location. A previous FIRR indicated this may be a permanent piece of equipment. The L shaped vent pipe was not observed on the location.

Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 3.** Looking west down the former access road. Desirable vegetation appears to have established on the access road and is progressing towards 80% coverage of the reference area.



**Photo 4.** Looking west across the tank battery location from the east side. Desirable vegetation is present on the location and appears to be progressing towards 80% coverage of the reference area. Undesirable vegetation such as kochia and list C noxious weed cheatgrass is present on the location.



Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 5.** Looking east across the tank battery location from the west side of the tank battery. See photo 4 comments.



**Photo 6.** Photo taken near the center of the tank battery looking east. List B noxious weed scotch thistle was observed on the location.



Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 7.** Looking south down the access road towards the well location. Desirable vegetation has established on the access road.



**Photo 8.** Looking east across the well location. Desirable vegetation has established on the well location.



Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 9.** Looking north from the wellbore area. See photo 8 comments.



**Photo 10.** Looking west from the wellbore area. See photo 8 comments.



Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 11.** Looking south from the wellbore area. See photo 8 comments.



**Photo 12.** Reference vegetation to the north of the tank battery location.



Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 13.** Picture taken near the wellbore location looking east. Powerline remains.



**Photo 14.** Looking west near the wellbore location. Powerline continues onward to well api 001-07435.

Inspection Photos  
Location Name: HILTON #1  
Location ID: 319953



**Photo 15.** This section of power line appears to have been installed for oil and gas and does not extend past well 001-07435.

