

Final Reclamation and Stormwater Inspection

January 20, 2026

Operator: WESTERN INTERIOR ENERGY INC - 95750

Location ID: 319966

Well Name: LUNDGREN #1

Inspection Document #: 718601309

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LUNDGREN #1
Location ID: 319966



Photo 1. Picture taken looking down the access road from well API 001-07539 towards the well location. Desirable vegetation appears to have established on the access road. The powerline that served this well remains in place along the access road.



Photo 2. Looking west down the access road towards the well location. The land transitions from non-cropland to cropland. The field is out of growing season at the time of inspection.



Inspection Photos
Location Name: LUNDGREN #1
Location ID: 319966



Photo 3. Looking east from the well area across the location. The electrical service terminates at this location and appears to be unused. The location is in cropland, fallow at the time of inspection.




Photo 4. Looking north from the wellbore. See photo 3 comments.

Inspection Photos
Location Name: LUNDGREN #1
Location ID: 319966



Photo 5. Looking west from the wellbore. See photo 3 comments.



Photo 6. Looking south from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: LUNDGREN #1
Location ID: 319966



Photo 7. Reference area to the north of the well location.

Inspection Photos
Location Name: LUNDGREN #1
Location ID: 319966



Photo 8. This section of power line appears to have been installed for oil and gas and does not extend past well 001-07435.

