

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0693 Entrance to location




Photo # 0723 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0696 Location



Photo # 0710 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0711 Location



Photo # 0720 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0735 SE corner of location



Photo # 0736 NE corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0737 NW corner of location



Photo # 0738 SW corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026




Photo # 0699 Weeds & weed debris near wellhead and pump jack presents a potential fire hazard

Photo # 0709 Weeds & weed debris near wellhead and pump jack presents a potential fire hazard

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0704 Staining on location around Pump Jack

Photo # 0706 Staining on location around Pump Jack

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #20-33 PAD

Location ID: 316158

Date: 01/6/2026



Photo # 0732 Weeds & weed debris in secondary containment presents a potential fire hazard

Photo # 0733 Weeds & weed debris in secondary containment presents a potential fire hazard