

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/12/2026

Submitted Date:

01/21/2026

Document Number:

719500818

FIELD INSPECTION FORM

Loc ID 335648 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283955	WELL	PR	05/15/2008	GW	045-12041	N. PARACHUTE WF11B K22 596	PR
283956	WELL	PR	03/30/2008	GW	045-12040	N. PARACHUTE WF06B K22 596	PR
283957	WELL	PR	03/07/2007	GW	045-12039	N. PARACHUTE WF05D K22 596	PR
283958	WELL	PR	02/01/2011	GW	045-12038	N. PARACHUTE WF16B K22 596	PR
283959	WELL	PR	03/07/2007	GW	045-12037	N. PARACHUTE WF05B K22 596	PR
283960	WELL	PR	01/17/2008	GW	045-12026	N. PARACHUTE WF16B-21 K22 59	PR
283961	WELL	PR	03/23/2006	GW	045-12027	N.PARACHUTE WF 12D K22 596	PR
283962	WELL	PR	03/07/2007	GW	045-12028	N. PARACHUTE WF09D K22 596	PR
283963	WELL	PR	03/23/2006	GW	045-12029	N.PARACHUTE WF 13B K22 596	PR
283965	WELL	PR	03/07/2007	GW	045-12031	N. PARACHUTE WF14B K22 596	PR
283966	WELL	PR	03/23/2006	GW	045-12032	N.PARACHUTE WF09B K22 596	PR
283967	WELL	PR	03/07/2007	GW	045-12033	N. PARACHUTE WF15D K22 596	PR
283968	WELL	PR	03/07/2007	GW	045-12034	N. PARACHUTE WF15B K22 596	PR
283988	WELL	PR	11/22/2007	GW	045-12035	N. PARACHUTE WF12B K22 596	PR

283991	WELL	PR	02/01/2014	GW	045-12036	N. PARACHUTE WF11D K22 596	PR
414496	WELL	PR	02/16/2011	GW	045-18858	N. Parachute WF04A-27 K22 59	PR
414498	WELL	PR	12/01/2023	GW	045-18859	N. Parachute WF03D-27 K22 59	PR
414499	WELL	PR	09/14/2011	GW	045-18860	N. Parachute WF03C-27 K22 59	PR
414510	WELL	PR	09/14/2011	GW	045-18861	N. Parachute WF04B-22 K22 59	PR
414734	WELL	PR	10/10/2011	GW	045-18870	N. Parachute WF15A-22 K22 59	PR
414736	WELL	PR	09/14/2011	GW	045-18871	N. Parachute WF05D-22 K22 59	PR
414739	WELL	PR	07/07/2011	GW	045-18872	N. Parachute WF10A-21 K22 59	PR
414749	WELL	PR	07/13/2011	GW	045-18877	N. Parachute WF04B-27 K22 59	PR
414751	WELL	PR	10/10/2011	GW	045-18878	N. Parachute WF06C-22 K22 59	PR
414752	WELL	PR	09/14/2011	GW	045-18879	N. Parachute WF14D-22 K22 59	PR
414754	WELL	PR	10/10/2011	GW	045-18880	N. Parachute WF11A-22 K22 59	PR
414756	WELL	PR	06/17/2011	GW	045-18881	N. Parachute WF11D-22 K22 59	PR
414758	WELL	PR	04/13/2011	GW	045-18883	N. Parachute WF10D-21 K22 59	PR
414760	WELL	PR	01/24/2014	GW	045-18884	N. Parachute WF14C-22 K22 59	PR
414763	WELL	PR	06/01/2025	GW	045-18887	N. Parachute WF15A-21 K22 59	PR
414764	WELL	PR	05/12/2011	GW	045-18888	N. Parachute WF13D-22 K22 59	PR
414767	WELL	PR	06/17/2011	GW	045-18890	N. PARACHUTE WF03A-27 K22 59	PR
414768	WELL	PR	01/24/2014	GW	045-18891	N. Parachute WF12B-22 K22 59	PR
414769	WELL	PR	04/13/2011	GW	045-18892	N. Parachute WF13C-22 K22 59	PR
414772	WELL	PR	06/17/2011	GW	045-18895	N. Parachute WF04D-22 K22 59	PR
414774	WELL	PR	07/13/2011	GW	045-18896	N. Parachute WF09B-21 K22 59	PR
414777	WELL	PR	04/13/2011	GW	045-18897	N. PARACHUTE WF08D-21 K22 59	PR
414779	WELL	PR	09/14/2011	GW	045-18898	N. Parachute WF06B-22 K22 59	PR
414780	WELL	PR	07/13/2011	GW	045-18899	N. Parachute WF04C-27 K22 59	PR
414783	WELL	PR	06/17/2011	GW	045-18901	N. Parachute WF04C-22 K22 59	PR
414786	WELL	PR	09/07/2010	GW	045-18903	N. Parachute WF13B-22 K22 59	PR
414788	WELL	PR	09/08/2010	GW	045-18904	N. Parachute WF12C-22 K22 59	PR
414793	WELL	PR	04/13/2011	GW	045-18908	N. Parachute WF09D-21 K22 59	PR
414797	WELL	PR	09/14/2011	GW	045-18911	N. Parachute WF05C-22 K22 59	PR

414802	WELL	PR	09/14/2011	GW	045-18914	N. Parachute WF03B-27 K22 59	PR
414806	WELL	PR	05/12/2011	GW	045-18916	N. Parachute WF10B-21 K22 59	PR
414807	WELL	PR	09/14/2011	GW	045-18917	N. Parachute WF14B-22 K22 59	PR
414816	WELL	PR	07/01/2022	GW	045-18919	N. Parachute WF16A-21 K22 59	PR
414819	WELL	PR	06/01/2018	GW	045-18920	N. Parachute WF16C-21 K22 59	PR
414821	WELL	PR	07/29/2010	GW	045-18921	N. Parachute WF16D-21 K22 59	PR
414822	WELL	PR	10/10/2011	GW	045-18922	N. Parachute WF15C-22 K22 59	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 1/12/2026 at approximately 13:45, Compliance Inspector Matthew Morris conducted a follow-up audit at QB ENERGY OPERATING LLC, N. Parachute/WF K22 596 at Location ID #335648 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Tags hung on the wells are missing required information (API number).		
Corrective Action:	Comply with Rule 605.d.	Date:	02/22/2026

Emergency Contact Number:			
Comment:	911/(970)285-2615		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Concrete barriers installed at gas meters/lift and ancillary equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe rails installed at pig station		
Corrective Action:		Date:	

Equipment:			
Type: Ancillary equipment	# 7		corrective date
Comment:	Line heaters		
Corrective Action:		Date:	
Type: Plunger Lift	# 11		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 12		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 11		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 11		
Comment:	Gas lift		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Generator		
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS			,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	283955	Type:	WELL	API Number:	045-12041	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283956	Type:	WELL	API Number:	045-12040	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283957	Type:	WELL	API Number:	045-12039	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283958	Type:	WELL	API Number:	045-12038	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283959	Type:	WELL	API Number:	045-12037	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283960	Type:	WELL	API Number:	045-12026	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283961	Type:	WELL	API Number:	045-12027	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	283962	Type:	WELL	API Number:	045-12028	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283963 Type: WELL API Number: 045-12029 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283965 Type: WELL API Number: 045-12031 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283966 Type: WELL API Number: 045-12032 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283967 Type: WELL API Number: 045-12033 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283968 Type: WELL API Number: 045-12034 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283988 Type: WELL API Number: 045-12035 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283991 Type: WELL API Number: 045-12036 Status: PR Insp. Status: PR

Producing Well			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414496	Type:	WELL
API Number:	045-18858	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414498	Type:	WELL
API Number:	045-18859	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414499	Type:	WELL
API Number:	045-18860	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414510	Type:	WELL
API Number:	045-18861	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414734	Type:	WELL
API Number:	045-18870	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414736	Type:	WELL
API Number:	045-18871	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414739	Type:	WELL
API Number:	045-18872	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	

Facility ID: 414749 Type: WELL API Number: 045-18877 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414751 Type: WELL API Number: 045-18878 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414752 Type: WELL API Number: 045-18879 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414754 Type: WELL API Number: 045-18880 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414756 Type: WELL API Number: 045-18881 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414758 Type: WELL API Number: 045-18883 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414760 Type: WELL API Number: 045-18884 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414763 Type: WELL API Number: 045-18887 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414764 Type: WELL API Number: 045-18888 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414767 Type: WELL API Number: 045-18890 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414768 Type: WELL API Number: 045-18891 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414769 Type: WELL API Number: 045-18892 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414772 Type: WELL API Number: 045-18895 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414774 Type: WELL API Number: 045-18896 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414777 Type: WELL API Number: 045-18897 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414779	Type:	WELL
API Number:	045-18898	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414780	Type:	WELL
API Number:	045-18899	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414783	Type:	WELL
API Number:	045-18901	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414786	Type:	WELL
API Number:	045-18903	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414788	Type:	WELL
API Number:	045-18904	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414793	Type:	WELL
API Number:	045-18908	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	414797	Type:	WELL
API Number:	045-18911	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID: 414802 Type: WELL API Number: 045-18914 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414806 Type: WELL API Number: 045-18916 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414807 Type: WELL API Number: 045-18917 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414816 Type: WELL API Number: 045-18919 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414819 Type: WELL API Number: 045-18920 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414821 Type: WELL API Number: 045-18921 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414822 Type: WELL API Number: 045-18922 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
				Material Handling And Spill Prevention		
		Other	Fail			Erosion onto lease road
Gravel						
		Ditches				
		Culverts				
		Compaction				
Compaction						

Comment: Rocks from cliff face have eroded onto lease road.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved. Install or repair required BMPs.

Date: 02/06/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) One sign is posted for all wells on location. Tags hung on the wells are missing required information (API number)</p> <p>2) Erosion onto lease road</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	01/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404514878	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7423414
719500819	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7423410