

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2026

Submitted Date:

01/22/2026

Document Number:

710500687

FIELD INSPECTION FORM

Loc ID: 324831 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
Waggoner, Kyle		kyle.waggoner@state.co.us	
L, Stacy		stacy@strachanexploration.com	Field inspections
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	06/01/2022	OW	061-06365	FRAZEE 2-6	EI
324831	LOCATION	AC			-	FRAZEE-619S50W 6NWNW	EI
486875	SPILL OR RELEASE	CL	07/01/2024		-	Frazee 2-6 Tank Battery	EI
489020	SPILL OR RELEASE	CL	12/18/2025		-	Frazee 2-6 Production Line	EI

General Comment:

This is a follow up Environmental Inspection for the Frazee 02-06 Well location located in Kiowa County, Colorado.

Location ID: 324831
API #: 05-061-06365
Spill ID: 486875
Spill ID: 489020
Remediation Project no. 35932

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	At the time of inspection, a barrel with soil was observed north of the access road. The lid for the barrel was not secured and laying on the ground.		
Corrective Action:	Comply with Rule 1002.f.(2).A. Implement BMP following good engineering practices to minimize contact with stormwater and precipitation.		Date: 01/27/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Fencing surrounding the Secondary Containment for the Tank Battery is not maintained. Reclamation Inspection Doc # 713601782 conducted on 01/16/2025 and Environmental Inspection Doc # 710500430 conducted on 2/24/2025 both identified the Tank Battery fencing as inadequate. Original CA date identified in Reclamation Inspection Doc # 713601782 shall apply		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1		OTHER		
Comment:	At the time of inspection, a plastic tank at the wellhead was blown over				
Corrective Action:	Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607				Date: 02/24/2026

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 213004 Type: WELL API Number: 061-06365 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 324831 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 486875 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 489020 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Environmental

Spill/Remediation:

Comment: This is a follow up Environmental Inspection for Remediation Project # 35932. At the time of inspection, impacted soil remains within the secondary containment area. Operator proposed a Bioremediation strategy to remediate the remaining impacted soils adjacent to the AST/within the secondary containment area. Impacts are to be remediated in situ via chemical oxidant to physically degrade hydrocarbons.

Impacted soil observed along the roadway and secondary containment berms in previous Reclamation and Environmental inspections has been evaluated, See Form 27-S document no. 404491689 for additional information.

At the time of inspection, impacted soils observed at the rear base of the pumping unit are still present. Operator shall clean up stained soils and securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Spill/Release ID 489020 has been closed. Additional remediation activities will proceed under Remediation Project no. 35932.

Corrective Action: **Operator shall continue Quarterly Reporting until the Site Assessment is completed, and the remediation area demonstrates Compliance with Full Table 915-1 Standards.** Date: 03/31/2026

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
All ongoing/unaddressed comments, Corrective Actions (CAs), and Conditions of Approval (COAs) from previous Forms remain applicable.	sanchezcc	01/22/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404515974	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424320
710500688	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424318