

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2026

Submitted Date:

01/22/2026

Document Number:

719001184

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
326300 \_\_\_\_\_ GARCIA, CHARLES \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**  
ECMC Operator Number: \_\_\_\_\_ 10133 \_\_\_\_\_  
Name of Operator: HILCORP ENERGY COMPANY \_\_\_\_\_  
Address: P O BOX 61229 \_\_\_\_\_  
City: \_\_\_\_\_ HOUSTON \_\_\_\_\_ State: \_\_\_\_\_ TX \_\_\_\_\_ Zip: \_\_\_\_\_ 77208 \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
9 \_\_\_\_\_ Number of Comments  
1 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216192	WELL	PR	10/01/2017	CBM	067-07798	HUBER-JOHNSON 1-33	PR

**General Comment:**  
Inspection Report Summary  
On 1/22/26 | Inspector Charles Garcia conducted an on-site inspection.  
Location: HUBER-JOHNSON 1-33  
API# 067-07798  
Operator: HILLCORP ENERGY COMPANY  
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Deadman # & Marked	# 4	corrective date	
Comment:	ALL MARKERS ARE DOWN		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	GAS ENGINE OVER HEATED AND CAUSED COOLENT HOSE TO BUST AND OVERFLOW COOLENT ON TO GROUND SEE LOCATION PICTURES		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND ENGINE SKID rule 1002.f	Date:	01/29/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216192 Type: WELL API Number: 067-07798 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 04/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404516429	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424748">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424748</a>
719001185	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424744">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7424744</a>