

**FORM  
INSP**

Rev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2026

Submitted Date:

01/28/2026

Document Number:

713302468

## FIELD INSPECTION FORM

Loc ID 482390 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

32 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ports@chevron.onmicrosoft.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482790	WELL	SI	01/01/2025	LO	123-51810	Drake 06N	SI
482791	WELL	PR	09/18/2024	OW	123-51811	Drake 07N	PR
482792	WELL	PR	09/20/2024	OW	123-51812	Drake 20N	PR
482793	WELL	PR	10/17/2024	OW	123-51813	Drake 24N	PR
482794	WELL	PR	09/22/2024	OW	123-51814	Drake 15N	PR
482795	WELL	PR	09/20/2024	OW	123-51815	Drake 17N	PR
482796	WELL	PR	09/01/2024	OW	123-51816	Drake 12N	PR
482797	WELL	PR	09/22/2024	OW	123-51817	Drake 14NA	PR
482798	WELL	PR	09/12/2024	OW	123-51818	Drake 05N	PR
482799	WELL	PR	09/19/2024	OW	123-51819	Drake 19NA	PR
482800	WELL	PR	09/21/2024	OW	123-51820	Drake 11N	PR
482801	WELL	PR	09/21/2024	OW	123-51821	Drake 10N	PR
482802	WELL	PR	09/20/2024	OW	123-51822	Drake 21N	PR
482803	WELL	PR	09/19/2024	OW	123-51823	Drake 18N	PR
482804	WELL	PR	09/20/2024	OW	123-51824	Drake 16N	PR
482805	WELL	PR	10/17/2024	OW	123-51825	Drake 23N	PR
482806	WELL	PR	09/10/2024	OW	123-51826	Drake 01N	PR
482807	WELL	PR	09/22/2024	OW	123-51827	Drake 13N	PR
482808	WELL	PR	09/21/2024	OW	123-51828	Drake 09NA	PR
482809	WELL	PR	09/22/2024	OW	123-51829	Drake 22N	PR
482810	WELL	PR	09/11/2024	OW	123-51830	Drake 03N	PR

482811	WELL	PR	09/18/2024	OW	123-51831	Drake 08N	PR
482812	WELL	PR	09/11/2024	OW	123-51832	Drake 02N	PR
482813	WELL	PR	09/12/2024	OW	123-51833	Drake 04NA	PR

**General Comment:**

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	good, twentyfour wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Plunger Lift	# 4				
Comment:					
Corrective Action:		Date:			
Type: Ancillary equipment	# 20				
Comment:	automation panels				
Corrective Action:		Date:			
Type: Bradenhead	# 20				
Comment:	piped to surface				
Corrective Action:		Date:			
Type: Bradenhead	# 4				
Comment:	piped to surface				
Corrective Action:		Date:			
Type: Plunger Lift	# 20				
Comment:					
Corrective Action:		Date:			
Type: Ancillary equipment	# 14				
Comment:	automation panels				
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 482790 Type: WELL API Number: 123-51810 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE  
 Comment: Valves appeared to be closed at time of inspection  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/02/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482791 Type: WELL API Number: 123-51811 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482792 Type: WELL API Number: 123-51812 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/15/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONE  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482793 Type: WELL API Number: 123-51813 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 05/09/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482794 Type: WELL API Number: 123-51814 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 05/14/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482795 Type: WELL API Number: 123-51815 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 05/14/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 20 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482796 Type: WELL API Number: 123-51816 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482797 Type: WELL API Number: 123-51817 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482798 Type: WELL API Number: 123-51818 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482799 Type: WELL API Number: 123-51819 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482800 Type: WELL API Number: 123-51820 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes  
Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482801 Type: WELL API Number: 123-51821 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes  
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482802 Type: WELL API Number: 123-51822 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/09/2025 Annual Brhd Completed? Yes  
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482803 Type: WELL API Number: 123-51823 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/14/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482804 Type: WELL API Number: 123-51824 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/14/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482805 Type: WELL API Number: 123-51825 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/09/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482806 Type: WELL API Number: 123-51826 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482807 Type: WELL API Number: 123-51827 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/03/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482808 Type: WELL API Number: 123-51828 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/15/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482809 Type: WELL API Number: 123-51829 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482810 Type: WELL API Number: 123-51830 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482811 Type: WELL API Number: 123-51831 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482812 Type: WELL API Number: 123-51832 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/27/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 62 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482813 Type: WELL API Number: 123-51833 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/13/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<u>Audit of scout card and related documents</u> <u>Routine inspection</u>  <u>This inspection does not nullify any orders or NOAV from the ECMC</u>	kesterm	01/28/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302469	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7430309">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7430309</a>