

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/29/2026

Submitted Date:

01/29/2026

Document Number:

708908375

FIELD INSPECTION FORM

Loc ID 334794 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: 401806899

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 29 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Toews, Wesley		wtoews@blm.gov	
TEP		ECMCInspectionReports@flywheelenergy.com	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199991	WELL	PR	08/02/2001	GW	045-07410	FEDERAL GM 41-8	PR
271758	WELL	PR	07/28/2004	OW	045-09944	FEDERAL GM 441-8	PR
271759	WELL	PR	05/01/2004	OW	045-09945	FEDERAL GM 541-8	PR
271760	WELL	PR	07/27/2004	GW	045-09946	FEDERAL GM 341-8	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	Signs weathered & cracking but still legible at this time		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:	1 Tank label has previous operators name - please refer to photo log		
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Dehy disconnected & not in use/unused equipment (Additionally equipment is not listed in operators FORM 2A - document # 401806899		
Corrective Action:	Comply with CECMC Rule 606		Date: 02/28/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
	Type OTHER		
Comment:	Unused dehy - hog panels		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Dehy disconnected & not in use/unused equipment (Additionally equipment is not listed in operators FORM 2A - document # 401806899)		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended piping on unused dehy/wildlife hazard/available for entry by wildlife/not in compliance with CECMC Rules 602 & 608		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	FEDERAL GM 41-8 & FEDERAL GM 341-8 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible. FEDERAL GM 441-8 & FEDERAL GM 541-8 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:	Paint peeling off production tank & tank starting to rust - please refer to photo log Tank equipped with telemetry				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	199991	Type:	WELL	API Number:	045-07410	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	271758	Type:	WELL	API Number:	045-09944	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	271759	Type:	WELL	API Number:	045-09945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
	After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414								
	Scout Card record coordinates for the FEDERAL GM 541-8 well appear to be off by approximately 123 ft								
Corrective Action:	Comply with CECMC Rules 216 & 414							Date:	01/03/2026
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	271760	Type:	WELL	API Number:	045-09946	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other				Rill erosion developing in some sections
Gravel						Sparse to none in areas
Other						Hay bales
		Ditches				
		Other				Hay bales
		Berms				
Compaction						Light compaction in some areas
		Rip Rap				
		Sediment Traps				
		Check Dams				
		Culverts				
		Gravel				Sparse to none in most sections
		Compaction				Light compaction in some sections
Slope Roughening						

Comment: [Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 01/29/2026 at approximately 13:03 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at TEP ROCKY MOUNTAIN LLC FEDERAL GM41-8 Pad Location # 334794 in Garfield County Colorado. Please refer to inspection/audit 708907928 conducted on 12/04/2025, previous corrective action has not been completed. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 266 yards from Riley Gulch. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Inspected Facilities - Coordinates for the FEDERAL GM 541-8 well appear to be incorrect - Comply with CECMC Rules 216 & 414 with a CA date of 01/03/2026 2. Housekeeping - Unused equipment on location - Comply with Rule 606 with a CA date of 02/28/2026 <p>Comments -</p> <p>Signs/Marker - 1 Tank label has previous operators name</p> <p>Equipment - Open ended piping on unused dehy/wildlife hazard/available for entry by wildlife</p> <p>Tanks & Berms - Paint peeling off production tank & tank starting to rust</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	01/29/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908376	Inspection/Audit 708908375 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7431773
708908377	Inspection/Audit 708908375 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7431774