

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2026

Submitted Date:

01/23/2026

Document Number:

701104453

**FIELD INSPECTION FORM**

Loc ID 334689 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285966	WELL	PR	07/31/2006	GW	045-12593	BOSELY SG 314-23	EG
285967	WELL	PR	08/01/2011	GW	045-12592	BOSELY SG 14-23	EG
285968	WELL	PR	07/31/2006	GW	045-12591	BOSELY SG 414-23	EG
285969	WELL	PR	07/31/2006	GW	045-12590	BOSELY SG 514-23	EG
423120	WELL	PR	02/22/2012	GW	045-20678	Bosely SG 544-22	EG
423133	WELL	PR	06/13/2012	GW	045-20679	Bosely SG 44-22	EG
423137	WELL	PR	06/13/2012	GW	045-20680	Bosely SG 444-22	EG
423139	WELL	PR	02/22/2012	GW	045-20681	Bosely SG 344-22	EG
432184	WELL	PR	11/07/2013	GW	045-21931	Bosely SG 702-23-HN1	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Unused flowline risers lack OOSLAT tags.  
Comply with CECMC Rule 1101  
CA Date 2/7/2026

**Location**

**Lease Road:**

Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume			
In Containment:	No				
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					

**Equipment:**

			corrective date
Type:	Flow Line # 2		
Comment:	Unused flowline risers lack OOSLAT tags.		
Corrective Action:	Comply with CECMC Rule 1101		Date: 02/07/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 285966 Type: WELL API Number: 045-12593 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 285967 Type: WELL API Number: 045-12592 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 285968 Type: WELL API Number: 045-12591 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 285969 Type: WELL API Number: 045-12590 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 423120 Type: WELL API Number: 045-20678 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 423133 Type: WELL API Number: 045-20679 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 423137 Type: WELL API Number: 045-20680 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 423139 Type: WELL API Number: 045-20681 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 432184 Type: WELL API Number: 045-21931 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404516968	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425235">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425235</a>
701104454	Flowline integrity inspection 701104453 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425232">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425232</a>