

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2026

Submitted Date:

01/23/2026

Document Number:

719001208

FIELD INSPECTION FORM

Loc ID 326076 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215826	WELL	PR	01/01/2022	CBM	067-07431	SMITH A 1	PR

General Comment:

[Inspection Report Summary](#)
On 1/23/26 | Inspector Charles Garcia conducted an on-site inspection.
Location: SMITH A 1
Operator: Simcoe LLC
API#: 067-07431
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK PLACARD DAMAGED SEE LOCATION PICTURES		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	2 TELEMETRY EQUIPMENT 1 LUBE OIL CONTAINER WITH SPILL PREVENTION		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	GAS		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.240900,-107.638800
Comment:	95 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 215826 Type: WELL API Number: 067-07431 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Fail					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Stormwater BMPs have been installed on the east portion of the pad. Additional erosion has been observed on the east edge of the pad. See location pictures

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 02/06/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404517636	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425878
719001209	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7425874