

Inspection Photos

API: 071-06297

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/29/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Standing at the access road facing northeast toward the reclaimed flowline ROW. There is erosion along this area that will need to be repaired, reseeded, and stabilized.



Inspection Photos



Photo 2. Facing toward the flowline area where erosion has occurred. This area will need to be repaired, reseeded, and stabilized.



Inspection Photos



Photo 3. Facing northeast along the access road. There is erosion along both sides of the road that will need to be repaired with BMP's.



Inspection Photos



Photo 4. There is a stormwater diversion at the switchback of the road that should have BMP's to prevent erosion such as rip/rap, checkdams. ect.



Inspection Photos



Photo 5. Facing northeast along the access road. BMP's along the roadside will need to be installed. The road has narrowed due to erosion of the roadbase along the road sides.



Inspection Photos



Photo 6. Further up the road the roadsides are stabilized with vegetation and gravel. Stormwater from this area of the road is directed down the road contributing to erosion shown in previous photos.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06297 | Date: 1/29/2026

Inspection Photos



Photo 7. Facing northeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06297 | Date: 1/29/2026

Inspection Photos



Photo 8. Facing southwest toward the meter shed where the well sign is installed. The wellsite utilizes the electric power line shown in the photo.



Inspection Photos



Photo 9. Facing north toward the cut slope. There are some bare areas that could benefit from hand seeding to establish more vegetation.

