

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7269 From entrance to location



Photo # 7270 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7271 Location



Photo # 7272 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7273 Location



Photo # 7274 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7275 Open ended load line




Photo # 7276 Dehy disconnected & not in use/unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7277 Piping on dehy disconnected/dehy not in use/unused equipment



Photo # 7278 Piping on dehy disconnected/dehy not in use/unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7279 Still column has been removed from dehy /dehy inoperable & not in use/unused equipment



Photo # 7280 Netting for methanol tank containment needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 32-4 Pad

Location ID: 334843



Photo # 7281 Netting for methanol tank containment needs maintenance/wildlife hazard



Photo # 7282 Netting for methanol tank containment needs maintenance/wildlife hazard