

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2026

Submitted Date:

01/30/2026

Document Number:

715203855

**FIELD INSPECTION FORM**

Loc ID 302988 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252214	WELL	PR	06/01/2015	GW	125-06082	EKBERG 1-22	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Trail through pasture	
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	WELLHEAD	
	Comment:	Lease signs mounted to meter shed	
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:	<input style="width: 95%;" type="text"/>	
	Corrective Action:	<input style="width: 95%;" type="text"/>	Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead, VGS and meter sheds	
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
	Comment:	Telemetry equipment and bellows meter (for domestic use)	
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
	Comment:	Shared meter run for (Ekberg 1-22, 3-22, BIBMA 12-22, Renzelman 11-22, 13-22, 14-22)	
Corrective Action:			Date:
Type: Vertical Separator	# 6		
	Comment:	6-Vertical gas separators 50% buried by meter sheds	
Corrective Action:			Date:

<b>Venting:</b>			
	Yes/No		
	Comment:		
Corrective Action:			Date:

<b>Flaring:</b>			
	Type		

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 252214 Type: WELL API Number: 125-06082 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Ekberg 1-22, 3-22, BIBMA 12-22, Renzelman 11-22, 13-22, 14-22\)](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203889	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7434091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7434091</a>