

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 0990 Entrance to location



Photo # 0991 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 0996 Location



Photo # 1014 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 1015 SW corner of location



Photo # 1016 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 1017 NE corner of location



Photo # 1006 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 1008 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Photo # 1009 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 1010 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Photo # 1011 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 1052 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.



Photo # 1054 Erosion & transport of sediment on cut slope, sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 01/14/2026



Photo # 1000 Location – Signage addressed