

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2026

Submitted Date:

01/26/2026

Document Number:

693809123

**FIELD INSPECTION FORM**

Loc ID 334464 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                                 | Comment         |
|------------------|--------------|---------------------------------------|-----------------|
| Browning, Chuck  | 970-433-4139 | chuck.browning@state.co.us            | Field Inspector |
| Labowskie, Steve |              | steve.labowskie@state.co.us           |                 |
| Energy, Laramie  |              | cogccnotifications@laramie-energy.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 297858      | WELL | PR     | 04/03/2013  | GW         | 077-09708 | NVEGA 2C-22-433D | PR          |

**General Comment:**

[ECMC Inspection/Audit Report Summary](#)

On January 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted a routine UIC inspection for LARAMIE ENERGY LLC 10433 on the NVega 2C Pad, Loc ID#334464, in Mesa County, Colorado.

Normal production operations were observed.

During the inspection/audit, the following compliance issues were observed:

- 1) Open ended flowlines on separator - Equipment does not properly prevent wildlife entrance or egress.

Any corrective action(s) from previous inspection that have not been addressed are still applicable

**Location**

|                    |          |  |       |
|--------------------|----------|--|-------|
| <b>Lease Road:</b> |          |  |       |
| Type               | Access   |  |       |
| comment:           |          |  |       |
| Corrective Action  |          |  | Date: |
| Type               | Main     |  |       |
| comment:           | CR 330 E |  |       |
| Corrective Action  |          |  | Date: |

Overall Good:

|                      |                      |  |       |
|----------------------|----------------------|--|-------|
| <b>Signs/Marker:</b> |                      |  |       |
| Type                 | TANK LABELS/PLACARDS |  |       |
| Comment:             |                      |  |       |
| Corrective Action:   |                      |  | Date: |
| Type                 | WELLHEAD             |  |       |
| Comment:             |                      |  |       |
| Corrective Action:   |                      |  | Date: |
| Type                 | BATTERY              |  |       |
| Comment:             |                      |  |       |
| Corrective Action:   |                      |  | Date: |

Emergency Contact Number:

|                    |              |  |             |
|--------------------|--------------|--|-------------|
| Comment:           | 800-891-6191 |  |             |
| Corrective Action: |              |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |             |  |       |
|--------------------|-------------|--|-------|
| <b>Fencing/:</b>   |             |  |       |
| Type               | WELLHEAD    |  |       |
| Comment:           | Panel fence |  |       |
| Corrective Action: |             |  | Date: |

|                       |     |  |                 |
|-----------------------|-----|--|-----------------|
| <b>Equipment:</b>     |     |  | corrective date |
| Type: Gas Meter Run   | # 1 |  |                 |
| Comment:              |     |  |                 |
| Corrective Action:    |     |  | Date:           |
| Type: Bird Protectors | # 1 |  |                 |
| Comment:              |     |  |                 |
| Corrective Action:    |     |  | Date:           |

|                                   |   |                  |
|-----------------------------------|---|------------------|
| Type: Flow Line                   | # 2   |                  |
| Comment:                          | Off location flowline risers with valves. 1- riser with blind flange  |                  |
| Corrective Action:                |   | Date:            |
| Type: Bradenhead                  | # 1   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Plunger Lift                | # 1   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Horizontal Heated Separator | # 1   |                  |
| Comment:                          | Open ended flowlines on separator -Equipment does not properly prevent wildlife entrance or egress.<br>See photos |                  |
| Corrective Action:                | Install or repair wildlife protection equipment to comply with rule 608.b.(7)                                     | Date: 02/02/2026 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE         | 2 | 400 BBLs | STEEL AST |         | 39.260665,-107.749700 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Wells Served By Facilities Above**

**AirsID**

|            |
|------------|
| API Number |
| 077-09708  |


|            |        |
|------------|--------|
| API Number | AirsID |
|------------|--------|

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |



**Inspected Facilities**

Facility ID: 297858 Type: WELL API Number: 077-09708 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/14/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                            |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|------------------------------------|
| Berms            | Pass            | Gravel                  | Pass                  | Material Handling And Spill Prevention | Pass                     | Secondary containment of chemicals |
| Drains           | Pass            | Culverts                | Pass                  |  |                          |                                    |
| Gravel           | Pass            | Ditches                 | Pass                  |  |                          |                                    |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p>On January 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted a routine UIC inspection for LARAMIE ENERGY LLC 10433 on the NVega 2C Pad, Loc ID#334464, in Mesa County, Colorado.</p> <p>Normal production operations were observed.</p> <p>During the inspection/audit, the following compliance issues were observed:<br/>                     1) Open ended flowlines on separator - Equipment does not properly prevent wildlife entrance or egress. Comply with rule 608.b.(7)</p> | browninc | 01/26/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 404519158    | INSPECTION SUBMITTED        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7426988">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7426988</a> |
| 693809131    | Inspection photos 1/23/2026 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7426985">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7426985</a> |