

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2026

Submitted Date:

01/26/2026

Document Number:

701104467

FIELD INSPECTION FORM

Loc ID 335310 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270272	WELL	PR	04/26/2004	GW	045-09513	BENZEL 26-9A (I26NW)	EG
270274	WELL	PR	05/11/2004	GW	045-09511	BENZEL 26-10A (26NW)	EG
270275	WELL	PR	04/10/2004	GW	045-09510	BENZEL 25-12B (I26NW)	EG
270311	WELL	PR	04/30/2004	GW	045-09524	BENZEL 26-9C	EG

General Comment:

[Flowline Integrity Spill Response Inspection / Tank Integrity Inspection](#)
Follow up to [12/31/2025 Inspection # 701104423](#)
Repair work (patches) have been made to tank top.
Dumpline repair made and test is scheduled for January 29th, 2026
Petroleum substance on well head flange.
Clean substance from flange and ground surface.
CA Date [02/06/2026](#)
Subsidence of ground near wells.
Back fill subsided hole at wells.
CA Date [02/06/2026](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
	WELLHEAD	<= 1 bbl		
Comment: Petroleum substance on well head flange.				
Corrective Action: Clean substance from flange and ground surface.				Date: 02/06/2026

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment: Repair work (patches) have been made to tank top.					
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 270272 Type: WELL API Number: 045-09513 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270274 Type: WELL API Number: 045-09511 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270275 Type: WELL API Number: 045-09510 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270311 Type: WELL API Number: 045-09524 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					Subsidence of ground near wells.

Comment: Subsidence of ground near wells.

Corrective Action: Back fill subsided hole at wells.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404519562	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7427365
701104469	Flowline integrity inspection 701104467 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7427364